

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/22/2025

Submitted Date:

10/24/2025

Document Number:

700300849

FIELD INSPECTION FORM

Loc ID 325806 Inspector Name: LABOWSKIE, STEVE On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10749
Name of Operator: SIMCOE LLC
Address: 1199 MAIN AVE SUITE 101
City: DURANGO State: CO Zip: 81301

Findings:

- 8 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, General		sjninspections@ikavenergy.com	All Inspections
Kosola, Jason		jason.kosola@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
215406	WELL	PR	04/15/1989	CBM	067-07011	HOTTER A 1	PR

General Comment:

[Follow-up inspection by SW Compliance Supervisor Steve labowskie to FIR doc#700300807.](#)
[Buired vessel inventoried in 2019 inspection doc# 687905406 has been removed, no Form 27 in well file per Rule 913.c](#)

Location			
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Emergency Contact Number:			
Comment:			Date: _____
Corrective Action:			
Good Housekeeping:			
Type	UNUSED EQUIPMENT		
Comment:	equipment not in use observed in previous inspection is no longer present		
Corrective Action:			Date:
Type	DEBRIS		
Comment:	Debris observed in previous inspection is no longer present.		
Corrective Action:			Date:
Type	OTHER		
Comment:	Appears coorrective action from previous inspection doc# 700300803 has been preformed. Area around compressor appears mostly cleaned up except right at edge of base of skid, appears that some lubricating oils may have seeped underneath, see photo		
Corrective Action:			Date:
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No _____			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Equipment:			
			corrective date
Type: Compressor	# 1		
Comment:	Compressor skid is free oif lube oil anbd not overflowing porom recent precipitation. No physical modifications or improvements have been made.		
Corrective Action:			Date:
Tanks and Berms:			
Contents	#	Capacity	Type
PRODUCED WATER	0	OTHER	PBV STEEL
Comment:	Buried vessel and earthen containment documented in doc# 674602032 are longer present		
Corrective Action:	Re-submit Form 27 or schedule sampling required for buried vessel removal and closure required by rule 913.c		Date: 01/02/2026
Paint			
Condition			

Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:					Date: <input style="width: 100px;" type="text"/>

Venting:

Yes/No	NO				
Comment:					
Corrective Action:					Date: <input style="width: 100px;" type="text"/>

Flaring:

Type					
Comment:					
Corrective Action:					Date: <input style="width: 100px;" type="text"/>

Inspected Facilities

Facility ID: 215406 Type: WELL API Number: 067-07011 Status: PR Insp. Status: PR

BradenHead

Date of Last Brhd Test: 06/08/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment: last Form 17 6/25/25 0 pressure

Corrective Action: _____

Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass					
Gravel	Pass					

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700300859	Well sign	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7297224
700300860	south side of compressor skid	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7297225
700300861	north sode of compressor skid	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7297226
700300862	wellhead area	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7297227
700300863	general area where buried tank and berms were	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7297228