

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CHEVRON GR 41-20 Pad

Location #: 335223



Photo # 914 From entrance to location




Photo # 915 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CHEVRON GR 41-20 Pad

Location #: 335223




Photo # 916 Location

Photo # 917 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CHEVRON GR 41-20 Pad

Location #: 335223



Photo # 918 Location




Photo # 919 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CHEVRON GR 41-20 Pad

Location #: 335223



Photo # 920 Location

Photo # 921 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CHEVRON GR 41-20 Pad

Location #: 335223



Photo # 922 Location



Photo # 923 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CHEVRON GR 41-20 Pad

Location #: 335223



Photo # 924 Location



Photo # 925 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CHEVRON GR 41-20 Pad

Location #: 335223



Photo # 926 Location



Photo # 927 Tank label on frac tank damaged & illegible