

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/21/2025

Submitted Date:

10/25/2025

Document Number:

708907713

**FIELD INSPECTION FORM**

Loc ID 335223 Inspector Name: Smelser, Wayne On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 96850  
Name of Operator: TEP ROCKY MOUNTAIN LLC  
Address: 1058 COUNTY ROAD 215  
City: PARACHUTE State: CO Zip: 81635

**Findings:**

18 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
TEP		ECMCInspectionReports@flywheelenergy.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
275425	WELL	PR	01/01/2019	GW	045-13533	CHEVRON GM 531-20	WK

**General Comment:**

[This is a Field Inspection/Audit of the scout card, related documents and the location.](#)

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective Action	L		Date:

Overall Good:

<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:	Tank label on frac tank damaged & illegible Spoke with TEP consultant & he had ordered another tank label & planned on getting it put on the tank asap.		
Corrective Action:			Date:
Type	BATTERY		
Comment:			
Corrective Action:			Date:
Type	OTHER		
Comment:	Rig sign at intersection of CR 215 & start of lease road		
Corrective Action:			Date:

<b>Emergency Contact Number:</b>		
Comment:	911/970-285-9377	
Corrective Action:		Date: _____

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			

<b>Equipment:</b>			corrective date
Type: Other	# 1		
Comment:	Workover rig		
Corrective Action:			Date:
Type: Other	# 1		
Comment:	Rig pump		
Corrective Action:			Date:
Type: Other	# 1		
Comment:	Wireline truck		
Corrective Action:			Date:
Type: Other	# 4		
Comment:	Fire extinguishers		
Corrective Action:			Date:

Type: Other	# 1		
Comment:	250 bbl rig tank		
Corrective Action:			Date:
Type: Other	# 1		
Comment:	500 bbl frac tank		
Corrective Action:			Date:
Type: Other	# 1		
Comment:	Accumulator		
Corrective Action:			Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 275425 Type: WELL API Number: 045-13533 Status: PR Insp. Status: WK

**Cement**

Cement Contractor

Contractor Name: \_\_\_\_\_

Contractor Phone: \_\_\_\_\_

Surface Casing

Cement Volume (sx): \_\_\_\_\_

Circulate to Surface: \_\_\_\_\_

Cement Fall Back: \_\_\_\_\_

Top Job, 1" Volume: \_\_\_\_\_

Intermediate Casing

Cement Volume (sxs): \_\_\_\_\_

Good Return During Job: \_\_\_\_\_

Production Casing

Cement Volume (sx): \_\_\_\_\_

Good Return During Job: \_\_\_\_\_

Plugging Operations

Depth Plugs(feet range): \_\_\_\_\_

Cement Volume (sx): \_\_\_\_\_

Good Return During Job: \_\_\_\_\_

Cement Type: \_\_\_\_\_

Comment: FORM 6 document # 404247003  
FORM 42 document #'s 404395819 & 404395824

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches				
Compaction						Light compaction
Gravel						Sparse to none
		Compaction				Light compaction
		Gravel				Sparse to none
		Culverts				

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**ECMC Comments**

Comment	User	Date
<p><a href="#">CECMC Inspection/Audit Report Summary</a>                      On 10/21/2025 at approximately 11:11 hours, I, Compliance Specialist, Wayne Smelser Conducted an on-site inspection/audit at TEP ROCKY MOUNTAIN LLC CHEVRON GR 41-20 Pad.                      Location # 335223 in Garfield County Colorado.                      Location is within High Priority/Density/Black Bear Habitat areas &amp; in close proximity to NSO Habitat area.                      Location is approximately 71 yards from Low Cost Ditch.                      Location is approximately 165 yards from Parachute Creek.                      While there, I observed P &amp; A operations on the CHEVRON GM 531-20 well.</p> <p>Comments -</p> <p>Signs/Marker - Tank label on frac tank damaged &amp; illegible</p> <p>Limited inspection due to ongoing P &amp; A operations on location</p> <p>This is a summary of inspection/audit report.</p>	smelserw	10/25/2025

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708907714	Inspection/Audit 708907713 photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7299366">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7299366</a>