

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC PUCKETT 21C-25 (MESA 10) Pad

Location #: 335105




Photo # 572 From entrance to location

Photo # 573 Location

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC PUCKETT 21C-25 (MESA 10) Pad

Location #: 335105



Photo # 574 Location



Photo # 575 Location

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC PUCKETT 21C-25 (MESA 10) Pad

Location #: 335105



Photo # 576 Location



Photo # 577 Location

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC PUCKETT 21C-25 (MESA 10) Pad

Location #: 335105



Photo # 578 Location



Photo # 579 Methanol tank lacks operator emergency #

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC PUCKETT 21C-25 (MESA 10) Pad

Location #: 335105



Photo # 580 Methanol tank lacks operator emergency #



Photo # 581 Methanol tank

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC PUCKETT 21C-25 (MESA 10) Pad

Location #: 335105



Photo # 582 Unused flowline lacks lockout tagout (OOSLAT)



Photo # 583 Unused flowline lacks lockout tagout (OOSLAT)

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC PUCKETT 21C-25 (MESA 10) Pad

Location #: 335105



Photo # 584 Unused flowline lacks lockout tagout (OOSLAT)



Photo # 585 Unused flowline lacks lockout tagout (OOSLAT)

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC PUCKETT 21C-25 (MESA 10) Pad

Location #: 335105



Photo # 586 Unmarked deadman



Photo # 587 Same unmarked deadman