

# Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC MESA P24-697 Pad

Location ID: 445862




Photo # 1185 From entrance to location

Photo # 1186 Location

# Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC MESA P24-697 Pad

Location ID: 445862



Photo # 1187 Location




Photo # 1188 Location

# Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC MESA P24-697 Pad

Location ID: 445862



Photo # 1189 Location



Photo # 1190 Location

# Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC MESA P24-697 Pad

Location ID: 445862




Photo # 1191 Location



Photo # 1192 Location

# Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC MESA P24-697 Pad

Location ID: 445862



Photo # 1193 Location



Photo # 1194 Location

# Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC MESA P24-697 Pad

Location ID: 445862



Photo # 1195 Location



Photo # 1196 Location

## Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC MESA P24-697 Pad

Location ID: 445862



**Photo # 1197 Open ended pipe near separators/wildlife hazard/available for entry by wildlife**



**Photo # 1198 Open ended pipe near separators/wildlife hazard/available for entry by wildlife**

## Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC MESA P24-697 Pad

Location ID: 445862



**Photo # 1199 PRV vent line does not comply with CECMC pressure safety device rules**



**Photo # 1200 PRV vent line does not comply with CECMC pressure safety device rules**

# Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC MESA P24-697 Pad

Location ID: 445862



**Photo # 1201 Rupture disc vent line does not comply with CECMC pressure safety device rules**



**Photo # 1202 PRV vent line does not comply with CECMC pressure safety device rules**

## Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC MESA P24-697 Pad

Location ID: 445862



**Photo # 1203 Rupture disc vent line does not comply with CECMC pressure safety device rules**



**Photo # 1204 Rupture disc vent line does not comply with CECMC pressure safety device rules**

## Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC MESA P24-697 Pad

Location ID: 445862



**Photo # 1205 Rupture disc vent line does not comply with CECMC pressure safety device rules**



**Photo # 1206 Rupture disc vent line does not comply with CECMC pressure safety device rules**

# Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC MESA P24-697 Pad

Location ID: 445862



**Photo # 1207 Rupture disc vent line does not comply with CECMC pressure safety device rules**

**Photo # 1208 Debris**

# Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC MESA P24-697 Pad

Location ID: 445862



Photo # 1209 Debris

Photo # 1210 Debris

# Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC MESA P24-697 Pad

Location ID: 445862



Photo # 1211 Unused equipment



Photo # 1212 Unused equipment

## Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC MESA P24-697 Pad

Location ID: 445862



Photo # 1213 Unused equipment



Photo # 1214 Cattle panels behind separator units laying on the ground

## Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC MESA P24-697 Pad

Location ID: 445862



Photo # 1215 Cattle panel around tank battery damaged



Photo # 1216 Cattle panel around tank battery damaged & laying on the ground