

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/21/2025

Submitted Date:

10/21/2025

Document Number:

720800090

FIELD INSPECTION FORM

Loc ID: 417683 Inspector Name: PETRIE, ERICA On-Site Inspection: 2A Doc Num: _____

Operator Information:

ECMC Operator Number: 83555
Name of Operator: SUNBURST INC
Address: P.O. BOX 140266
City: EDGEWATER State: CO Zip: 80214

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 10 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Jackson, Jay	303-781-3044	sun1045@aol.com	Principal Agent

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
417686	WELL	SI	02/01/2025	OW	123-31719	Joker 36-9-62	SI

General Comment:

This is a Well and Tank Battery Field Compliance Audit of the Scout Card, Related Documents and the Location.

Location

Overall Good:

Signs/Marker:

Type	BATTERY				
Comment:	Adequte - Sign at Entrance				
Corrective Action:				Date:	

Emergency Contact Number:

Comment:					
Corrective Action:				Date:	_____

Good Housekeeping:

Type	WEEDS				
Comment:	Overgrown Vegetation on entire site; see photos				
Corrective Action:	Comply with Rule 606 and 1003.f			Date:	11/04/2025

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	LOCATION				
Comment:	Barbed Wire				
Corrective Action:				Date:	

Equipment:

	Type	#			corrective date
Type: Bradenhead		# 1			
Comment:	Appears to be plumbed to surface				
Corrective Action:				Date:	
Type: Pump Jack		# 1			
Comment:					
Corrective Action:				Date:	
Type: Other		# 1			
Comment:	Propane Tank (500 Gallons)				
Corrective Action:				Date:	
Type: Prime Mover		# 1			
Comment:	Gas Engine				
Corrective Action:				Date:	
Type: Vertical Heater Treater		# 1			
Comment:					
Corrective Action:				Date:	

Type: Emission Control Device	# 1		
Comment:			
Corrective Action:			Date:
Type: Flare	# 1		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	400 BBLs	STEEL AST		
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	Shares berm with the Crude			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	400 BBLs	STEEL AST		40.710003,-104.275281
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No		
Comment:		
Corrective Action:		
		Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 417686 Type: WELL API Number: 123-31719 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action: Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404399561	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7290607
720800091	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7290599