

Inspection Photos
Facility 9 Flowline
Facility ID 478843



**Photo 1 – Spill excavation with pipelines/flowlines.
Fence down for active work**

Photo 2 - Spill excavation with pipelines/flowlines

Inspection Photos
Facility 9 Flowline
Facility ID 478843



Photo 3 – Pipelines/flowlines in open excavation



**Photo 4 - Spill excavation with pipelines/flowlines.
Fence down for active work**

Inspection Photos
Facility 9 Flowline
Facility ID 478843



Photo 5 – Pothole adjacent to flowline shows impacted soil. Fence down for active work.

Photo 6 - Pothole adjacent to flowline shows impacted soil. Fence down for active work.

Inspection Photos
Facility 9 Flowline
Facility ID 478843



Photo 7 – Impacted soil excavated from pothole adjacent to pipelines/flowlines. Fence down for active work

Photo 8 - Impacted soil being loaded on truck to be disposed of off location. Fence down for active work

Inspection Photos
Facility 9 Flowline
Facility ID 478843



Photo 9 – 8” KPK pipeline marker east of spill location

Photo 10 - 10” KPK pipeline marker east of spill location