

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/27/2025

Submitted Date:

10/28/2025

Document Number:

701104296

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: _____ On-Site Inspection
316152 _____ LONGWORTH, MIKE _____ 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10844
Name of Operator: QB ENERGY OPERATING LLC
Address: 1001 17TH STREET SUITE 1600
City: DENVER State: CO Zip: 80202

Findings:

- 3 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
,		ecmc.inspections@qb-energy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
232245	WELL	PR	05/16/2012	GW	103-09916	LOVE RANCH 2	EG

General Comment:

Flowline Integrity Inspection
Battery sign is at the gate on CR 5. Not all the information is correct: wrong Location id number (316201) wrong access road (CR20) lat/long not matching wellhead. No api # on sign.
Install sign to comply with Rule 605.e. CA Date 11/24/2025
Metal tag on sells line. No api#.
Install sign to comply with Rule 605.d. CA Date 11/24/2025

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	Metal tag on sells line. No api#.		
Corrective Action:	Install sign to comply with Rule 605.d.	Date:	11/28/2025
Type	BATTERY		
Comment:	Battery sign is at the gate on CR 5. Not all the information is correct: wrong Location id number (316201) wrong access road (CR20) lat/long not matching wellhead. No api # on sign.		
Corrective Action:	Install sign to comply with Rule 605.e.	Date:	11/28/2025

Emergency Contact Number:

Comment:	<input type="text"/>	Date:	<input type="text"/>
Corrective Action:	<input type="text"/>		

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No			
Comment:	<input type="text"/>		
Corrective Action:		Date:	<input type="text"/>

Flaring:

Type			
Comment:	<input type="text"/>		
Corrective Action:		Date:	<input type="text"/>

Inspected Facilities

Facility ID: 232245 Type: WELL API Number: 103-09916 Status: PR Insp. Status: EG

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
701104297	Flowline integrity inspection 701104296 photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7305536