

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/27/2025

Submitted Date:

10/28/2025

Document Number:

719000788

FIELD INSPECTION FORM

Loc ID: 333963 Inspector Name: GARCIA, CHARLES On-Site Inspection: 2A Doc Num: _____

Operator Information:

ECMC Operator Number: 53255
Name of Operator: MARALEX RESOURCES INC
Address: P O BOX 338
City: IGNACIO State: CO Zip: 81137

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 10 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		pbechtolt@maralexinc.com	
, O'hare		mollieo@maralexinc.com	San Juan inspections
Labowskie, Steve		steve.labowskie@state.co.us	
Longworth, Mike		mike.longworth@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
276035	WELL	SI	06/01/2025	CBM	067-09016	KEEGAN PATRICK 33-7-11 2A	SI
298720	WELL	PR	08/01/2025	CBM	067-09631	KEEGAN PATRICK 33-7-11 3C	PR

General Comment:

Inspection Report Summary
On 10/27/25 I Inspector Charles Garcia conducted an on-site inspection.
Location:KEEGAN PATRICK 33-7-11 #2A
Operator:MARALEX RESOURCES INC
API#: 067-09016, API# 067-09631
County: LaPlata

Location			
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	LOCATION SIGNS		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	970-563-4000 911 EMERGENCY		
Corrective Action:			Date:
Good Housekeeping:			
Type	WEEDS		
Comment:	OVERGROWN VEGATATION AROUND ALL EQUIPMENT SEE LOCATION PICTURES		
Corrective Action:	Keep areas around wellheads, tanks and separators clear of weeds (potentially combustible material) per Rule 610.k Control weeds and undesirable vegetation per Rule 606".		Date: 11/04/2025
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment: <input style="width: 100%;" type="text"/>			
<input type="checkbox"/> Multiple Spills and Releases?			
Equipment:			
Type: Prime Mover			# 2
Comment:			GAS
Corrective Action:		Date:	
Type: Ancillary equipment			# 3
Comment:			TELEMETRY EQUIPMENT 2 LUBE OIL CONTAINERS WITH SPILL PREVENTION
Corrective Action:		Date:	
Type: Deadman # & Marked			# 4
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors			# 2
Comment:			
Corrective Action:		Date:	
Type: Pump Jack			# 2
Comment:			
Corrective Action:		Date:	
Type: Flow Line			# 2
Comment:			

Corrective Action:		Date:	
Type: Gas Meter Run	# 2		
Comment:			
Corrective Action:		Date:	
Type: Other	# 2		
Comment:	METER HOUSES CALIBRATION IN COMPLIANCE		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 2		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 2		
Comment:			
Corrective Action:		Date:	
Type: Other	# 2		
Comment:	WELLHEADS		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	DOMESTIC TAP NOT SHOWING IN RELATED FACILITIES		
Corrective Action:	Submit an eForm 44 Flowline Report per Rule 1101.c.	Date:	01/28/2026

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 276035 Type: WELL API Number: 067-09016 Status: SI Insp. Status: SI

BradenHead

Date of Last Brhd Test: 10/04/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONE
 End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 298720 Type: WELL API Number: 067-09631 Status: PR Insp. Status: PR

Producing Well

Comment:

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 10/04/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 12 Fluid Type: NONE
 End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
719000793	LOCATION PICTURES	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7305893