

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/27/2025

Submitted Date:

10/28/2025

Document Number:

719000789

FIELD INSPECTION FORM

Loc ID: 334004 Inspector Name: GARCIA, CHARLES On-Site Inspection: 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 53255
Name of Operator: MARALEX RESOURCES INC
Address: P O BOX 338
City: IGNACIO State: CO Zip: 81137

Findings:

- 10 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Bechtolt, Phoebe		pbechtolt@maralexinc.com	
Labowskie, Steve		steve.labowskie@state.co.us	
,		mollieo@maralexinc.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
297197	WELL	SI	02/01/2025	CBM	067-09599	ARTFGANCE 33-7-14 3B	SI
297213	WELL	SI	06/01/2025	CBM	067-09605	ARTFGANCE 33-7-14 1	SI

General Comment:

Inspection Report Summary
On 10/27/25 I Inspector Charles Garcia conducted an on-site inspection.
Location:ART F GANCE 33-7-14 3 B, 33-7-14 #1
Operator:MARALEX RESOURCES INC
API#: 067-09599,API# 067-09605
County: LaPlata

Location			
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	LOCATION SIGNS		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	970-563-4000 911 EMERGENCY		
Corrective Action:			Date:
Good Housekeeping:			
Type	WEEDS		
Comment:	OVERGROWN VEGETATION DRY WEEDS AROUND ALL EQUIPMENT SEE LOCATION PICTURES		
Corrective Action:	Keep areas around wellheads, tanks and separators clear of weeds (potentially combustible material) per Rule 610.k Control weeds and undesirable vegetation per Rule 606".		Date: 11/04/2025
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Equipment:			
Type: Other	# 2	corrective date	
Comment:	METER HOUSES		
Corrective Action:			Date:
Type: Prime Mover	# 2		
Comment:			
Corrective Action:			Date:
Type: Other	# 1		
Comment:	CHEMICAL INJECTION CONTAINER WITH SPILL PREVENTION		
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 2		
Comment:			
Corrective Action:			Date:
Type: Flow Line	# 2		
Comment:			
Corrective Action:			Date:
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:			Date:

Type: Other	# 2		
Comment:	WELL HEADS		
Corrective Action:			Date:
Type: Pump Jack	# 2		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 3		
Comment:	TELEMETRY EQUIPMENT LUBE OIL CONTAINER WITH SPILL PREVENTION FOR PRIMR MOVERS		
Corrective Action:			Date:
Type: Gas Meter Run	# 2		
Comment:	GAS		
Corrective Action:			Date:
Type: Bradenhead	# 2		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:			Date:

Venting:

Yes/No			
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities

Facility ID: 297197 Type: WELL API Number: 067-09599 Status: SI Insp. Status: SI

BradenHead

Date of Last Brhd Test: 06/05/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 297213 Type: WELL API Number: 067-09605 Status: SI Insp. Status: SI

BradenHead

Date of Last Brhd Test: 06/05/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 1 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			
Compaction	Pass	Compaction	Pass	Material Handling And Spill Prevention	Pass	

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
719000794	LOCATION PICTURES	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7305894