

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/28/2025

Submitted Date:

10/28/2025

Document Number:

719000798

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: GARCIA, CHARLES On-Site Inspection
 325666 _____ 2A Doc Num: _____

Operator Information:

ECMC Operator Number: 10133
 Name of Operator: HILCORP ENERGY COMPANY
 Address: P O BOX 61229
 City: HOUSTON State: TX Zip: 77208

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

10 Number of Comments
1 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, General		FarmingtonRegulatoryTechs@hilcorp.com	SJB inspect
Labowskie, Steve		steve.labowskie@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
215196	WELL	PR	06/11/2001	CBM	067-06801	J R 12-2	PR
419425	WELL	PR	12/06/2010	CBM	067-09833	TIFFANY 32-7 12 6	PR

General Comment:

[Inspection Report Summary](#)
 On 10/28/25 I Inspector Charles Garcia conducted an on-site inspection.
 Location: TIFFANY 32-7 12-6, JR #12-2
 Operator:HILCORP ENERGY COMPANY
 API#: 067-06801 API#: 067-09833
 County: LaPlata

Location			
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	LOCATION SIGN		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	505-324-5170 911 EMERGENCY		
Corrective Action:			Date:
Overall Good: <input checked="" type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	PUMP JACK		
Comment:	CATTLE PANELS		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	CATTLE PANELS		
Corrective Action:			Date:
Equipment:			
			corrective date
Type: Pump Jack	# 2		
Comment:			
Corrective Action:			Date:
Type: Flow Line	# 2		
Comment:			
Corrective Action:			Date:
Type: Prime Mover	# 2		
Comment:	ELECTRIC		
Corrective Action:			Date:
Type: Other	# 2		
Comment:	METER HOUSES CALIBRATION IN COMPLIANCE		
Corrective Action:			Date:
Type: Vertical Heated Separator	# 2		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 2		

Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 2		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 4		
Comment:	TELEMETRY EQUIPMENT ELECTRIC PANELS		
Corrective Action:			Date:
Type: Other	# 2		
Comment:	WELLHEADS PACKING LEAK ON THE JR #12-2 PRODUCED WATER OVER FLOWING ON TO GROUND SEE LOCATION PICTURES		
Corrective Action:	Protection of soils Comply with 1002.c		Date: 10/29/2025

Venting:

Yes/No			
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities

Facility ID: 215196 Type: WELL API Number: 067-06801 Status: PR Insp. Status: PR

Producing Well

Comment:		
Corrective Action:		Date:

BradenHead

Date of Last Brhd Test: 06/17/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment:

Corrective Action: Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 419425 Type: WELL API Number: 067-09833 Status: PR Insp. Status: PR

Producing Well

Comment:		
Corrective Action:		Date:

BradenHead

Date of Last Brhd Test: 06/17/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 2 Fluid Type: _____

End Surf Csg Pressure: 0

Comment:

Corrective Action: Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
719000799	LOCATION PICTURES	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7305890