

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/22/2025

Submitted Date:

10/22/2025

Document Number:

713302265

**FIELD INSPECTION FORM**

Loc ID 311479 Inspector Name: Kester, Michael On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 47120  
Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP  
Address: P O BOX 173779  
City: DENVER State: CO Zip: 80217-

**Findings:**

- 13 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
, KerrMcGee	970-515-1500	ECMCInspections@Oxy.com	<a href="#">all inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
435980	WELL	PR	08/01/2015	OW	123-38886	BARCLAY 16C-26HZ	PR
436055	WELL	PR	08/01/2015	OW	123-38906	BARCLAY 16N-26HZ	PR
436057	WELL	PR	08/01/2015	OW	123-38907	BARCLAY 26N-11HZ	PR

**General Comment:**

[well site inspection](#)

**Location**

Overall Good:

**Signs/Marker:**

	Type WELLHEAD		
	Comment: <span style="color: blue;">good, three wells</span>		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:  Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

	Type WELLHEAD		
	Comment: <span style="color: blue;">metal panels</span>		
Corrective Action:		Date:	

**Equipment:**

					corrective date
Type: Ancillary equipment	# 5				
Comment:	<span style="color: blue;">automation/electrical panels</span>				
Corrective Action:		Date:			
Type: Plunger Lift	# 3				
Comment:					
Corrective Action:		Date:			
Type: Bradenhead	# 3				
Comment:	<span style="color: blue;">piped to surface</span>				
Corrective Action:		Date:			

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 435980 Type: WELL API Number: 123-38886 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR, Valves appeared to be open at time of inspection

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 07/11/2024 Annual Brhd Completed? No

Last Brhd Test Results Initial Surf Csg Pressure: 1 Fluid Type: None

End Surf Csg Pressure: --

Comment: Required reports not filed.  
Submit Bradenhead report...Last Bradenhead test report submitted 7-11-24

11/21/2025

Corrective Action: Comply with Rule 207

Date:

**Workover**

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 436055 Type: WELL API Number: 123-38906 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR, Valves appeared to be open at time of inspection

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 07/11/2024 Annual Brhd Completed? No

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: None

End Surf Csg Pressure: --

Comment: Required reports not filed.  
Submit Bradenhead report...Last Bradenhead test report submitted 7-11-24

11/21/2025

Corrective Action: Comply with Rule 207

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 436057 Type: WELL API Number: 123-38907 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR, Valves appeared to be open at time of inspection

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 07/11/2024 Annual Brhd Completed? No

Last Brhd Test Results Initial Surf Csg Pressure: 5 Fluid Type: None

End Surf Csg Pressure: --

Comment: Required reports not filed.  
Submit Bradenhead report...Last Bradenhead test report submitted 7-11-24

11/21/2025

Corrective Action: Comply with Rule 207

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**ECMC Comments**

Comment	User	Date
<p>Inspector Michael Kester, did audit scout card and related documents conducted on-site inspection.                      Location: Barclay 16C-26Hz                      Operator: Kerr McGee                      API#: 123-38886                      County: Weld                      While there, I observed well site with equipment.                      During this inspection the following possible compliance issues were observed:</p> <p>Bradenead test reporting Rule 207, corrective action date 11-21-2025, all three wells on site</p> <p>Weather conditions: sunny and dry                      A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with ECMC rules.                      This inspection does not nullify any orders or NOAV from the ECMC</p>	kesterm	10/22/2025

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404401396	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7292778">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7292778</a>
713302266	site pic	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7292774">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7292774</a>