

<b>FORM</b> <b>INSP</b> Rev X/20	<b>State of Colorado</b> <b>Energy and Carbon Management Commission</b> 1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109	 	Inspection Date: <u>10/22/2025</u> Submitted Date: <u>10/22/2025</u> Document Number: <u>719000758</u>
<b>FIELD INSPECTION FORM</b>			

Loc ID 333718      Inspector Name: GARCIA, CHARLES      On-Site Inspection       2A Doc Num: \_\_\_\_\_

**Operator Information:**

ECMC Operator Number: 10133

Name of Operator: HILCORP ENERGY COMPANY

Address: P O BOX 61229

City: HOUSTON      State: TX      Zip: 77208

**Status Summary:**

THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

11 Number of Comments  
2 Number of Corrective Actions  
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM  
 PREVIOUS INSPECTIONS THAT HAVE NOT  
 BEEN ADDRESSED ARE STILL APPLICABLE

**Contact Information:**

Contact Name	Phone	Email	Comment
, General		FarmingtonRegulatoryTechs@hilcorp.com	SJB inspect
Labowskie, Steve		steve.labowskie@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
258905	WELL	PR	01/04/2001	CBM	067-08389	MCCULLOCH 34-10 27-3	PR
295108	WELL	SI	08/01/2025	CBM	067-09515	SO UTE FC 34-10 27-7	SI

**General Comment:**

[Inspection Report Summary](#)  
 On 10/22/25 I Inspector Charles Garcia conducted an on-site inspection.  
 Location: MCCULLOCH 34-10 27-3 SO UTE FC 34-10  
 API# 067-08389 API# 067-09515  
 Operator: HILLCORP ENERGY COMPANY  
 County: LaPlata

Location			
Overall Good: <input checked="" type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	OTHER		
Comment:	LOCATION SIGN AT WELLHEAD		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	PRODUCED WATER TANK LABLE NOT LEGIBLE NEEDS REPLACED SEE LOCATION PICTURES		
Corrective Action:	Install sign or correct sign per rule 605	Date:	10/29/2025
Emergency Contact Number:			
Comment:	24 Hr #970-247-6916 Emergency #911		
Corrective Action:		Date:	
Overall Good: <input checked="" type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	SEPARATOR		
Comment:	HOG WIRE		
Corrective Action:		Date:	
<b>Equipment:</b>			
Type: Flow Line			corrective date
	# 2		
Comment:			
Corrective Action:		Date:	
Type: Other			
	# 2		
Comment:	METER HOUSES CALIBRATION IN COMPLIANCE		
Corrective Action:		Date:	
Type: Pump Jack			
	# 2		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors			
	# 2		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead			
	# 2		
Comment:			
Corrective Action:		Date:	

Type: Gas Meter Run	# 2		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 4		
Comment:	2 TELEMETRY EQUIPMENT 2 LUBE OIL CONTAINER WITH SPILL PREVENTION FOR PRIME MOVER		
Corrective Action:			Date:
Type: Pig Station	# 1		
Comment:			
Corrective Action:			Date:
Type: Prime Mover	# 2		
Comment:	GAS		
Corrective Action:			Date:
Type: Other	# 2		
Comment:	WELLHEADS		
Corrective Action:			Date:
Type: Deadman # & Marked	# 6		
Comment:			
Corrective Action:			Date:
Type: Vertical Heated Separator	# 2		
Comment:			
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	OTHER		37.158100,-107.925700
Comment:					
Corrective Action:					Date:

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO	
Comment:		

Corrective Action:		Date:	
--------------------	--	-------	--

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	



**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			
Compaction	Pass	Compaction	Pass			
Other	Fail					

Comment: **STORM WATER WASH OUT ON EAST SIDE OF LOCATION SEE LOCATION PICTURES**

Corrective Action: **Stormwater management Erosion Control Install or repair required BMPs per Rule 1002.f. (2)C**

Date: 11/22/2025

**Pits:**     NO SURFACE INDICATION OF PIT

Type: \_\_\_\_\_ Lined: \_\_\_\_\_ Pit ID: \_\_\_\_\_ Lat: \_\_\_\_\_ Long: \_\_\_\_\_

Reference Point: \_\_\_\_\_ Other: \_\_\_\_\_ Length: \_\_\_\_\_ Width: \_\_\_\_\_

**Lining:**

Liner Type: \_\_\_\_\_ Liner Condition: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action

\_\_\_\_\_

Date: \_\_\_\_\_

**Fencing:**

Fencing Type: \_\_\_\_\_ Fencing Condition: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action

\_\_\_\_\_

Date: \_\_\_\_\_

**Netting:**

Netting Type: \_\_\_\_\_ Netting Condition: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action

\_\_\_\_\_

Date: \_\_\_\_\_

Anchor Trench Present: \_\_\_\_\_ Oil Accumulation: \_\_\_\_\_ 2+ feet Freeboard: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action

\_\_\_\_\_

Date: \_\_\_\_\_

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404401508	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7292921">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7292921</a>
719000759	LOCATION PICTURES	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7292917">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7292917</a>