

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/20/2025

Submitted Date:

10/22/2025

Document Number:

719700237

**FIELD INSPECTION FORM**

Loc ID 326993 Inspector Name: Evins, Bret On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**

ECMC Operator Number: 69175  
Name of Operator: PDC ENERGY INC  
Address: 1099 18TH STREET SUITE 1500  
City: DENVER State: CO Zip: 80202

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

- 15 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
,		dnr_ecmc_engineering@state.co.us	
,		rbucogccinspectionreports@chevron.onmicrosoft.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
246182	WELL	SI	01/01/2025	GW	123-13979	STATE LEASE 81 23-16	TA

**General Comment:**

\*This is an audit of the scout card and related documents followed by a field audit.

Location			
<b>Lease Road:</b>			
Type	Access		
comment:	Adequate		
Corrective Action:			Date:
Overall Good: <input type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	OOSLAT applied at well, separator(s).		
Corrective Action:			Date:
<b>Emergency Contact Number:</b>			
Comment:	Posted.		
Corrective Action:			Date: _____
<b>Good Housekeeping:</b>			
Type	WEEDS		
Comment:	CORRECTIVE ACTION Item(s): 1.) Overgrown vegetation at wellsite(s). Refer to Rule 606.c for guidance.		
Corrective Action:	*Remove, manage, & control overgrown vegetation around wellsite(s). Comply with Rule 606.c. (14-days). See photo(s) #1.		Date: <u>11/05/2025</u>
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Iron panel.		
Corrective Action:			Date:
<b>Equipment:</b>			
Type: Bradenhead	# 1		corrective date
Comment:	Appears plumbed to surface.		
Corrective Action:			Date:
Type: Other	# 1		
Comment:	Wellhead: w/ Master, casing valves.		
Corrective Action:			Date:
Type: Plunger Lift	# 0		
Comment:	Temporarily Abandoned   TA. Equipment removed.		
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		40.478921,-104.555226

Comment: Centralized Battery serves 1 Location ID (326993).  
 (Well(s): 1: Temporarily Abandoned | TA).  
 Centralized Battery serves 1 Tank Battery Facility ID (481570).

Corrective Action:		Date:	
--------------------	--	-------	--

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**

Facility ID: 246182 Type: WELL API Number: 123-13979 Status: SI Insp. Status: TA

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTED

Comment: Temporarily Abandoned | TA.  
Well disconnected from flowline.  
Locked-Out, Tagged-Out | LOTO.  
OOSLAT applied. Date: 02/15/2025.  
ECMC records last prod: 12/2024.  
  
Form 4 on file. TA date: 12/10/2024. Approval Pending.  
DH-RBP set.  
Pressure tested RBP, Csg to 1500# for 15min. 12/11/2024.  
Form 5A on file. TA date: 12/10/2024. Approved.

Corrective Action:

Date: \_\_\_\_\_

**BradenHead**

Date of Last Brhd Test: 01/03/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 14 Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

**ECMC Comments**

Comment	User	Date
<p><b>CECMC Audit Report Synopsis:</b></p> <p>On FRI 10/20/2025 at approximately 13:36 hrs. I, Bret Evins, conducted an onsite audit at:                      Operator Name: PDC ENERGY INC                      Location Name: STATE LEASE 81-66N64W/16NESW                      Location ID: 326993                      Well Name(s) &amp; API:                      Reference:                      See "Inspected Facilities" section on page 1 of this report.                      Location County: Weld County, Colorado                      Weather: Mostly Sunny, dry.</p> <p>While there, I observed:                      Well(s): 1: Temporarily Abandoned   TA.                      Battery: Inactive   Shut-down.</p> <p>*CORRECTIVE ACTION Item(s):                      1.) See "Good Housekeeping" section on page 2 of this report.</p> <p>Routine audit.</p> <p>*Any Corrective Actions from prior audits that have not been addressed remain applicable.</p>	evinsb	10/22/2025

<p><b>CECMC Audit Report Synopsis:</b></p> <p>On FRI 10/20/2025 at approximately 13:36 hrs. I, Bret Evins, conducted an onsite audit at:                  Operator Name: PDC ENERGY INC                  Location Name: STATE LEASE 81-66N64W/16NESW                  Location ID: 326993                  Well Name(s) &amp; API:                  Reference:                  See "Inspected Facilities" section on page 1 of this report.                  Location County: Weld County, Colorado                  Weather: Mostly Sunny, dry.</p> <p>While there, I observed:                  Well(s): 1: Temporarily Abandoned   TA.                  Battery: Inactive   Shut-down.</p> <p>*CORRECTIVE ACTION Item(s):                  1.) See "Good Housekeeping" section on page 2 of this report.</p> <p>Routine audit.</p> <p>*Any Corrective Actions from prior audits that have not been addressed remain applicable.</p>	<p>evinsb</p>	<p>10/22/2025</p>
---	---------------	-------------------

<p>This is a WELL audit.                  Well(s): 1: Temporarily Abandoned   TA.                  Battery: Inactive   Shut-down.</p> <p>Centralized Battery serves 1 Location ID (326993).                  (Well(s): 1: Temporarily Abandoned   TA).</p> <p>Centralized Battery serves 1 Tank Battery Facility ID (481570).</p> <p>Reference (Associated Well(s), Battery Audits):                  A.) Field Audit Report doc. #719700237 and/or Location ID #326993 for TA Well(s) info.                  B.) Field Audit Report doc. #719700036 and/or Facility ID #481570 for Battery / Facility, Equipment info.</p>	<p>evinsb</p>	<p>10/22/2025</p>
---	---------------	-------------------

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404400656	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7291853">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7291853</a>
719700238	Audit photo(s)	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7291847">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7291847</a>