

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/28/2025

Submitted Date:

10/28/2025

Document Number:

713302288

**FIELD INSPECTION FORM**

Loc ID 484897 Inspector Name: Kester, Michael On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 10583  
Name of Operator: PETRO OPERATING COMPANY LLC  
Address: 9033 E EASTER PLACE SUITE 112  
City: CENTENNIAL State: CO Zip: 80112-

**Findings:**

16 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

| Contact Name | Phone | Email                               | Comment |
|--------------|-------|-------------------------------------|---------|
| ,            |       | andy.peterson@iptenergyservices.com |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 485241      | WELL | PR     | 07/01/2025  | OW         | 123-52224 | LG Everist 01 | PR          |
| 485242      | WELL | PR     | 07/01/2025  | OW         | 123-52225 | LG Everist 02 | PR          |
| 485243      | WELL | PR     | 07/01/2025  | OW         | 123-52226 | LG Everist 03 | PR          |
| 485244      | WELL | PR     | 07/01/2025  | OW         | 123-52227 | LG Everist 04 | PR          |
| 485245      | WELL | PR     | 07/01/2025  | OW         | 123-52228 | LG Everist 05 | PR          |
| 485246      | WELL | PR     | 07/01/2025  | OW         | 123-52229 | LG Everist 06 | PR          |
| 485247      | WELL | PR     | 07/01/2025  | OW         | 123-52230 | LG Everist 07 | PR          |

**General Comment:**

[well site and facility inspection](#)

**Location**

Overall Good:

**Signs/Marker:**

|                    |                      |       |  |
|--------------------|----------------------|-------|--|
| Type               | TANK LABELS/PLACARDS |       |  |
| Comment:           | good                 |       |  |
| Corrective Action: |                      | Date: |  |
| Type               | WELLHEAD             |       |  |
| Comment:           | good, seven wells    |       |  |
| Corrective Action: |                      | Date: |  |
| Type               | BATTERY              |       |  |
| Comment:           | good                 |       |  |
| Corrective Action: |                      | Date: |  |

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

| Type | Area | Volume |  |  |
|------|------|--------|--|--|
|      |      |        |  |  |

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

|                    |  |       |  |
|--------------------|--|-------|--|
| Type               |  |       |  |
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |

**Equipment:**

|                               |     |       |                 |
|-------------------------------|-----|-------|-----------------|
| Type: FWKO                    | # 3 |       | corrective date |
| Comment:                      |     |       |                 |
| Corrective Action:            |     | Date: |                 |
| Type: Vertical Heater Treater | # 1 |       |                 |
| Comment:                      |     |       |                 |
| Corrective Action:            |     | Date: |                 |
| Type: Pig Station             | # 2 |       |                 |
| Comment:                      |     |       |                 |
| Corrective Action:            |     | Date: |                 |
| Type: Gas Meter Run           | # 1 |       |                 |
| Comment:                      |     |       |                 |
| Corrective Action:            |     | Date: |                 |
| Type: Plunger Lift            | # 7 |       |                 |

|                                   |                               |  |       |
|-----------------------------------|-------------------------------|--|-------|
| Comment:                          |                               |  |       |
| Corrective Action:                |                               |  | Date: |
| Type: VRU                         | # 1                           |  |       |
| Comment:                          |                               |  |       |
| Corrective Action:                |                               |  | Date: |
| Type: Compressor                  | # 4                           |  |       |
| Comment:                          |                               |  |       |
| Corrective Action:                |                               |  | Date: |
| Type: Ancillary equipment         | # 13                          |  |       |
| Comment:                          | electric/automation panels    |  |       |
| Corrective Action:                |                               |  | Date: |
| Type: Horizontal Heated Separator | # 7                           |  |       |
| Comment:                          |                               |  |       |
| Corrective Action:                |                               |  | Date: |
| Type: LACT                        | # 1                           |  |       |
| Comment:                          |                               |  |       |
| Corrective Action:                |                               |  | Date: |
| Type: Bradenhead                  | # 7                           |  |       |
| Comment:                          | piped to surface, seven wells |  |       |
| Corrective Action:                |                               |  | Date: |
| Type: Bird Protectors             | # 9                           |  |       |
| Comment:                          |                               |  |       |
| Corrective Action:                |                               |  | Date: |
| Type: Emission Control Device     | # 1                           |  |       |
| Comment:                          |                               |  |       |
| Corrective Action:                |                               |  | Date: |

**Tanks and Berms:**

| Contents           | #                  | Capacity | Type  | Tank ID | SE GPS |
|--------------------|--------------------|----------|-------|---------|--------|
| PRODUCED WATER     | 1                  | 500 BBLs | OTHER |         |        |
| Comment:           | V bottom frac tank |          |       |         |        |
| Corrective Action: |                    |          |       |         | Date:  |

**Paint**

|                  |          |
|------------------|----------|
| Condition        | Adequate |
| Other (Content)  |          |
| Other (Capacity) |          |
| Other (Type)     |          |

**Berms**

| Type     | Capacity         | Permeability (Wall) | Permeability (Base) | Maintenance |
|----------|------------------|---------------------|---------------------|-------------|
|          |                  |                     |                     |             |
| Comment: | same containment |                     |                     |             |

|                    |   |          |           |         |        |
|--------------------|---|----------|-----------|---------|--------|
| Corrective Action: |   |          |           |         | Date:  |
| Contents           | # | Capacity | Type      | Tank ID | SE GPS |
| PRODUCED WATER     | 2 | 300 BBLs | STEEL AST |         |        |
| Comment:           |   |          |           |         |        |
| Corrective Action: |   |          |           |         | Date:  |

**Paint**

|                  |          |  |
|------------------|----------|--|
| Condition        | Adequate |  |
| Other (Content)  |          |  |
| Other (Capacity) |          |  |
| Other (Type)     |          |  |

**Berms**

|                    |          |                     |                     |             |
|--------------------|----------|---------------------|---------------------|-------------|
| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| Metal              | Adequate | Walls Sufficient    | Base Sufficient     | Adequate    |
| Comment:           |          |                     |                     |             |
| Corrective Action: |          |                     |                     |             |
|                    |          |                     |                     | Date:       |

**Venting:**

|                    |    |       |
|--------------------|----|-------|
| Yes/No             | NO |       |
| Comment:           |    |       |
| Corrective Action: |    | Date: |

**Flaring:**

|                    |       |
|--------------------|-------|
| Type               |       |
| Comment:           |       |
| Corrective Action: | Date: |

**Inspected Facilities**

Facility ID: 485241 Type: WELL API Number: 123-52224 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR, Valves appeared to be open at time of inspection

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 07/26/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 485242 Type: WELL API Number: 123-52225 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR, Valves appeared to be open at time of inspection

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 07/26/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 485243 Type: WELL API Number: 123-52226 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR, Valves appeared to be open at time of inspection

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 07/26/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 485244 Type: WELL API Number: 123-52227 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR, Valves appeared to be open at time of inspection

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 07/26/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 3 Fluid Type: NONE  
 End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 485245 Type: WELL API Number: 123-52228 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR, Valves appeared to be open at time of inspection

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 07/26/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONE  
 End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 485246 Type: WELL API Number: 123-52229 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR, Valves appeared to be open at time of inspection

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 07/26/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONE  
 End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 485247 Type: WELL API Number: 123-52230 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR, Valves appeared to be open at time of inspection

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 07/26/2025 Annual Brhd Completed? \_\_\_\_\_

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment:

Corrective Action:  Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**ECMC Comments**

| Comment   | User    | Date       |
|---|---------|------------|
|   | kesterm | 10/28/2025 |
| Audit of scout card and related documents<br>Routine inspection   | kesterm | 10/28/2025 |
| This inspection does not nullify any orders or NOAV from the ECMC |         |            |

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL   |
|--------------|-------------|---|
| 713302289    | site pic    | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7306143">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7306143</a> |