

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC PUCKETT 12A-24D (MESA 11) Pad

Location ID: 335455



Photo # 1767 From entrance to location

Photo # 1768 Location

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC PUCKETT 12A-24D (MESA 11) Pad

Location ID: 335455




Photo # 1769 Location



Photo # 1770 Location

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC PUCKETT 12A-24D (MESA 11) Pad

Location ID: 335455




Photo # 1771 Location




Photo # 1772 Location

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC PUCKETT 12A-24D (MESA 11) Pad

Location ID: 335455



Photo # 1773 Location



Photo # 1774 Location

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC PUCKETT 12A-24D (MESA 11) Pad

Location ID: 335455



Photo # 1775 Location



Photo # 1776 Debris

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC PUCKETT 12A-24D (MESA 11) Pad

Location ID: 335455



Photo # 1777 Debris

Photo # 1778 Debris

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC PUCKETT 12A-24D (MESA 11) Pad

Location ID: 335455



Photo # 1779 Open ended piping on separator/wildlife hazard/available for entry by wildlife



Photo # 1780 Flame arrester housing missing cover/wildlife hazard/available for entry by wildlife

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC PUCKETT 12A-24D (MESA 11) Pad

Location ID: 335455



**Photo # 1781 Open ended pipe on fire tube/wildlife hazard
/available for entry by wildlife**



**Photo # 1782 Flame arrester housing missing cover/wildlife
hazard/available for entry by wildlife**

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC PUCKETT 12A-24D (MESA 11) Pad

Location ID: 335455



**Photo # 1783 Fire tube open ended/wildlife hazard
/available for entry by wildlife**