

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/20/2025

Submitted Date:

10/23/2025

Document Number:

701104286

**FIELD INSPECTION FORM**

Loc ID: 324283 Inspector Name: LONGWORTH, MIKE On-Site Inspection:  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 10433  
Name of Operator: LARAMIE ENERGY LLC  
Address: 1700 LINCOLN ST STE 3950  
City: DENVER State: CO Zip: 80203

**Findings:**

- 4 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
COGCC, Laramie	970-248-0497	cogccnotifications@laramie-energy.com	All inspections

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
273551	WELL	PR	01/01/2005	GW	045-10258	OXY FEDERAL 708-11	EG

**General Comment:**

Flowline Integrity Inspection and Tank Integrity Inspection  
Follow up to 10-01-2025 inspection 701104271  
Tank has been emptied and repairs are in process.  
No OOSLAT for dump line while out of service.  
Install lock and tag for OOSLAT. CA Date 10/24/2025

**Location**

Overall Good:

**Signs/Marker:**

Type	OTHER		
Comment:	No OOSLAT for dump line while out of service.		
Corrective Action:	Install lock and tag for OOSLAT.	Date:	10/24/2025

**Emergency Contact Number:**

Comment:

Corrective Action:  Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

**Tanks and Birms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	300 BBLs	STEEL AST		,
Comment:	Repairs in process. Hatch cover is removed and leaned against the opening. Continue to block access to wildlife.				
Corrective Action:					Date:

Paint

Condition	<input style="width: 800px;" type="text"/>				
Other (Content)	<input style="width: 800px;" type="text"/>				
Other (Capacity)	<input style="width: 800px;" type="text"/>				
Other (Type)	<input style="width: 800px;" type="text"/>				

Birms


Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	<input style="width: 800px;" type="text"/>			
Corrective Action:				Date:

**Venting:**

Yes/No	<input style="width: 800px;" type="text"/>			
Comment:	<input style="width: 800px;" type="text"/>			
Corrective Action:				Date:

**Flaring:**

Type	<input style="width: 800px;" type="text"/>			
Comment:	<input style="width: 800px;" type="text"/>			
Corrective Action:				Date:



**Inspected Facilities**

Facility ID: 273551 Type: WELL API Number: 045-10258 Status: PR Insp. Status: EG

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404401849	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7293380">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7293380</a>
701104287	Flowline integrity inspection 701104286 photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7293377">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7293377</a>