

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/15/2025

Submitted Date:

10/23/2025

Document Number:

716301651

FIELD INSPECTION FORM

Loc ID 322265 Inspector Name: Beardslee, Tom On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 44390
Name of Operator: JAVERNICK OIL
Address: 3040 E MAIN
City: CANON CITY State: CO Zip: 81212

Findings:

- 8 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Greager, Meredith		meredith.greager@state.co.us	
Javernick, James	719-275-3040/719-671-3787	javernick1@gmail.com	All Inspections
Javernick, Salene		salenej@gmail.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210087	WELL	PR	08/01/2024	OW	043-40024	ROB HIAWATHA 2	PR

General Comment:

"This is a field audit of the scout card, related documents and the location."

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

corrective date

Type: Pump Jack # 1

Comment: ELECTRIC DRIVE

Corrective Action:

Date:

Type: Bradenhead # 1

Comment: Bradenhead inaccessible or not visible(wellhead tree does not appear to include a Bradenhead in it original install). ATTACHED IS OPERATOR REQUEST FOR VARIANCE.

Corrective Action:

Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	100 BBLs	STEEL AST		38.326278,-105.124334

Comment:

Corrective Action:

Date:

Paint

Condition Adequate

Other (Content)

Other (Capacity)

Other (Type)

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate

Comment:

Corrective Action:

Date:

Venting:

Yes/No NO

Comment:

Corrective Action:

Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 210087 Type: WELL API Number: 043-40024 Status: PR Insp. Status: PR

Producing Well

Comment: pr

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 02/23/2022 Annual Brhd Completed? _____

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment: Bradenhead inaccessible or not visible(wellhead tree does not appear to include a Bradenhead in it original install). ATTACHED IS OPERATOR REQUEST FOR VARIANCE. NOTE: A BRHD TEST WAS SUBMITTED IN 2022 WITH NO ACCESS TO BRHD.

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Optical Gas Imaging Survey

Survey Type: Routine

Current Operations: Production Workover Flowback Referred to APCD

GPS(entrance of location): Lat: 38.326278 Long: -105.124334

Wind: Light Speed: 5 (mph) Direction From: north Weather: Partly Temperature: 81 (F)

Assisting Staff: _____ Camera #: _____

Visible Smoke Referred to CDPHE

Comment: GUAGE HATCH IS LEAKING GAS CONSTANTLY

Corrective Action: Tanks will function as sealed and ventless with gas released only through a vapor control system or properly sized pressure relief valve. per Rule 608.a.(9). Date: 10/16/2025

ECMC Comments

Comment	User	Date
<p style="color: blue;">THIS IS A FOLLOW UP TO INSP #716300177, CA'S HAVE BEEN ADDRESSED HOWEVER THERE IS A NEW CA. ECMC Inspection Report Summary On Tuesday 10-15-2025 at approximately 13:21, I Tom Beardslee Conducted an on-site inspection an Evergreen Natural Resources location ROBB HIAWATHA 2 API# 05-043-40024 in Las Animas County Colorado. While there, I observed production operation. During this inspection the following possible compliance issues were observed: GUAGE HATCH LEAKING, Rule 608.a.(9). CA DATE 10-16-2025 A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with ECMC rules.</p>	beardslt	10/23/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404402828	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7294181
716301652	INSP. PHOTOS	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7294179
716301653	FLIRR VIDEO OF GUAGE HATCH	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7294180