

FORM INSP Rev X/20	State of Colorado Energy and Carbon Management Commission 1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109	 	Inspection Date: <u>10/22/2025</u> Submitted Date: <u>10/23/2025</u> Document Number: <u>719000761</u>
FIELD INSPECTION FORM			

Loc ID 306992 Inspector Name: GARCIA, CHARLES On-Site Inspection
 2A Doc Num: _____

Status Summary:

THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

10 Number of Comments
1 Number of Corrective Actions
 Corrective Action Response Requested

Operator Information:

ECMC Operator Number: 10133
 Name of Operator: HILCORP ENERGY COMPANY
 Address: P O BOX 61229
 City: HOUSTON State: TX Zip: 77208

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, General		FarmingtonRegulatoryTechs@hilcorp.com	SJB inspect
Labowskie, Steve		steve.labowskie@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
290877	WELL	PR	02/01/2011	CBM	067-09374	ARGENTA 34-10 34-1A	PR

General Comment:

[Inspection Report Summary](#)
 On 10/22/25 I Inspector Charles Garcia conducted an on-site inspection.
 Location: ARGENTA 34-10 34-1A
 API# 067-09374
 Operator: HILLCORP ENERGY COMPANY
 County: LaPlata
 SHARED LOCATION WITH ARGENTA 34-10 34-1

Location			
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	LOCATION SIGN		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	24 Hr #970-247-6916 Emergency #911		Date:
Corrective Action:			
Overall Good: <input checked="" type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Equipment:			
			corrective date
Type: Other	# 2		
Comment:	WELLHEADS		
Corrective Action:			Date:
Type: Flow Line	# 2		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 2		
Comment:			
Corrective Action:			Date:
Type: Deadman # & Marked	# 6		
Comment:	2 UNMARKED		
Corrective Action:			Date:
Type: Vertical Heated Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 7		
Comment:	6 TELEMETRY EQUIPMENT 1 LUBE OIL CONTAINERS		
Corrective Action:			Date:
Type: Other	# 1		
Comment:	METER HOUSE		
Corrective Action:			Date:
Type: Gas Meter Run	# 2		
Comment:			

Corrective Action:		Date:	
Type: Pump Jack	# 2		
Comment:			
Corrective Action:		Date:	
Type: Prime Mover	# 2		
Comment:	GAS		
Corrective Action:		Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Fail	Gravel	Pass			
Compaction	Fail	Compaction	Pass			

Comment: DEEP RUTS ACROSS LOCATION SEE LOCATION PICTURES

Corrective Action: PER RULE 1002.f and "maintain facility",

Date: 01/23/2026

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404403134	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7294472
719000763	LOCATION PICTURES	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7294466