

FORM INSP Rev X/20	State of Colorado Energy and Carbon Management Commission 1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109	 	Inspection Date: <u>10/23/2025</u> Submitted Date: <u>10/23/2025</u> Document Number: <u>719000771</u>
FIELD INSPECTION FORM			

Loc ID 333793 Inspector Name: GARCIA, CHARLES On-Site Inspection 2A Doc Num: _____

Status Summary:

THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

9 Number of Comments
3 Number of Corrective Actions
 Corrective Action Response Requested

Operator Information:

ECMC Operator Number: 56680
 Name of Operator: MERRION OIL & GAS CORP
 Address: 610 REILLY AVENUE
 City: FARMINGTON State: NM Zip: 87401

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Thompson, Philana	(505) 324-5300	pthompson@merrion.bz	
Labowskie, Steve		steve.labowskie@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
285806	WELL	PR	12/01/2020	CBM	067-09209	BETELGEUSE 1	PR
292295	WELL	PR	03/01/2024	CBM	067-09391	RIGEL 1	PR

General Comment:

Inspection Report Summary
 On 10/23/25 | Inspector Charles Garcia conducted an on-site inspection.
 Location: RIGEL #1, BETELGEUSE #1
 Operator: MERRION OIL & GAS CORP
 API#: 067-09209 API#067-09391
 County: LaPlata

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	LOCATION SIGNS		
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:	PRODUCED WATER TANK HAS NO LABELS OR PLACARDS SEE LOCATION PICTURES		
Corrective Action:	Install sign or correct sign per rule 605		Date: 10/30/2025

Emergency Contact Number:

Comment:	505-324-5300 911 EMERGENCY		
Corrective Action:			Date:

Good Housekeeping:

Type	WEEDS		
Comment:	OVERGROWN VEGATATION ON LOCATION SEE LOCATION PICTURES		
Corrective Action:	Control weeds and undesirable vegetation per Rule 606".		Date: 10/30/2025

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type					corrective date
Type: Other	# 2				
Comment:	WELL HEADS				
Corrective Action:					Date:
Type: Flow Line	# 2				
Comment:					
Corrective Action:					Date:
Type: Gas Meter Run	# 2				
Comment:	CALIBRATION IN COMPLIANCE				
Corrective Action:					Date:
Type: Bradenhead	# 2				
Comment:					
Corrective Action:					Date:
Type: Vertical Heated Separator	# 2				
Comment:					

Corrective Action:		Date:	
Type: Plunger Lift	# 2		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 2		
Comment:	TELEMETRY EQUIPMENT		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	PBV STEEL		37.092600,-107.574200
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	PLASTIC LINED BERM FILLING UP WITH STORM WATER SEE LOCATION PICTURES			
Corrective Action:	"Maintain adequate freeboard in spill prevention to prevent overflow. Fluid is discolored and may have some product mixed in, fluid should be disposed as waste in approved manner for type of chemical used"			Date:
				10/30/2025

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 285806 Type: WELL API Number: 067-09209 Status: PR Insp. Status: PR

Producing Well

Comment:		
Corrective Action:		Date:

BradenHead

Date of Last Brhd Test: 11/05/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment:

Corrective Action: Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 292295 Type: WELL API Number: 067-09391 Status: PR Insp. Status: PR

Producing Well

Comment:		
Corrective Action:		Date:

BradenHead

Date of Last Brhd Test: 11/05/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment:

Corrective Action: Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404403136	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7294474
719000772	LOCATION PICTURES	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7294469