

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/30/2025

Submitted Date:

10/30/2025

Document Number:

719700269

FIELD INSPECTION FORM

Loc ID 326993 Inspector Name: Evins, Bret On-Site Inspection 2A Doc Num: _____

Operator Information:

ECMC Operator Number: 69175
Name of Operator: PDC ENERGY INC
Address: 1099 18TH STREET SUITE 1500
City: DENVER State: CO Zip: 80202

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

8 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		rbucogccinspectionreports@c hevron.onmicrosoft.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
246182	WELL	SI	01/01/2025	GW	123-13979	STATE LEASE 81 23-16	TA

General Comment:

*This is an audit of the scout card and related documents followed by an AMA. (Alternate Method Audit).

Location

Overall Good:

Signs/Marker:

	Type WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	Posted.		
Corrective Action:		Date:	

Good Housekeeping:

Type	WEEDS		
Comment:	<p>Prior audit: CORRECTIVE ACTION ITEM(s): Overgrown vegetation at wellsite(s). Refer to Rule 606.c for guidance. *Remove, manage, & control overgrown vegetation around wellsite(s). Comply with Rule 606.c. (30 days). CA date: 11/05/2025.</p> <p>This audit: *FIR Resolution Form FIRR doc. #404414242 asserts: Overgrown vegetation around wellsite has been mitigated as of 10/29/2025. Operator provided photo for verification. See photo(s) #1, 2.</p>		
Corrective Action:		Date:	

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

	Type: Plunger Lift	# 0		corrective date
Comment:	Temporarily Abandoned TA. Equipment removed.			
Corrective Action:		Date:		

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 246182 Type: WELL API Number: 123-13979 Status: SI Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTED

Comment: Temporarily Abandoned | TA.
Well disconnected from flowline.
Locked-Out, Tagged-Out | LOTO.
OOSLAT applied. Date: 02/15/2025.
ECMC records last prod: 12/2024.

Form 4 on file. TA date: 12/10/2024. Approval Pending.
DH-RBP set.
Pressure tested RBP, Csg to 1500# for 15min. 12/11/2024.
Form 5A on file. TA date: 12/10/2024. Approved.

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 01/03/2025 Annual Brhd Completed? Yes
Last Brhd Test Results Initial Surf Csg Pressure: 14 Fluid Type: _____
End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
<p>CECMC Audit Report Synopsis:</p> <p>On THU 10/30/2025 at approximately 10:00 hrs. I, Bret Evins, conducted an AMA: Alternate Method Audit at: Operator Name: PDC ENERGY INC Location Name: STATE LEASE 81-66N64W/16NESW Location ID: 326993 Well Name(s) & API: Reference: See "Inspected Facilities" section on page 1 of this report. Location County: Weld County, Colorado Weather: Mostly Sunny, dry.</p> <p>Audit observations: Well(s): 1: Temporarily Abandoned TA. Battery: Inactive Shut-down.</p> <p>*While conducting this audit, the following prior possible compliance issues appear to be addressed: *CORRECTIVE ACTION Item(s) RESOLUTION Comment: Refer to pg 2, "Good Housekeeping" section of this report.</p> <p>*FIR Resolution Form FIRR doc. #404414242 asserts: Overgrown vegetation around wellsite has been mitigated as of 10/29/2025. Operator provided photo for verification. See photo(s) #1, 2.</p> <p>Routine audit.</p> <p>*Any Corrective Actions from prior audits that have not been addressed remain applicable.</p>	evinsb	10/30/2025

<p>This is a WELL audit. (AMA: Alternate Method Audit). Well(s): 1: Temporarily Abandoned TA. Battery: Inactive Shut-down.</p> <p>Centralized Battery serves 1 Location ID (326993). (Well(s): 1: Temporarily Abandoned TA).</p> <p>Centralized Battery serves 1 Tank Battery Facility ID (481570).</p> <p>*Follow-up to Field Audit Report doc. #719700237 dated 10/20/2025. *Follow-up to FIR Resolution Form (FIRR) doc. #404414242 dated 10/29/2025.</p>	<p>evinsb</p>	<p>10/30/2025</p>
--	---------------	-------------------

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
719700270	Audit photo(s)	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7309248