

Inspection Photos
Location Name: Pan Am B 4,6,10,12
Spill ID: 485939



Locations where Landowner's fencing was torn down

Locations where Landowner's fencing was torn down

Inspection Photos
Location Name: Pan Am B 4,6,10,12
Spill ID: 485939



Locations where Landowner's fencing was torn down

Locations where Landowner's fencing was torn down

Inspection Photos
Location Name: Pan Am B 4,6,10,12
Spill ID: 485939



Open excavation and fallen fencing

Open excavation and fallen fencing



Inspection Photos
Location Name: Pan Am B 4,6,10,12
Spill ID: 485939



Open excavation and fallen fencing

Open excavation and fallen fencing



Inspection Photos
Location Name: Pan Am B 4,6,10,12
Spill ID: 485939



Open excavation and fallen fencing



Open excavation and fallen fencing



Inspection Photos
Location Name: Pan Am B 4,6,10,12
Spill ID: 485939



Monitoring well



Open excavation and fallen fencing

Inspection Photos
Location Name: Pan Am B 4,6,10,12
Spill ID: 485939



Stockpile left onsite

Open excavation and fallen fencing



Inspection Photos
Location Name: Pan Am B 4,6,10,12
Spill ID: 485939



Large stockpile location that was removed

Large stockpile location that was removed



Inspection Photos
Location Name: Pan Am B 4,6,10,12
Spill ID: 485939



Stockpile left onsite. Weeds

Stockpile left onsite. Weeds



Inspection Photos
Location Name: Pan Am B 4,6,10,12
Spill ID: 485939



Stockpile left onsite. Weeds

Stockpile left onsite. Weeds



Inspection Photos
Location Name: Pan Am B 4,6,10,12
Spill ID: 485939



Torn excavation fencing



Weeds. Torn excavation fencing



Inspection Photos
Location Name: Pan Am B 4,6,10,12
Spill ID: 485939



Weeds

Inspection Photos
Location Name: Pan Am B 4,6,10,12
Spill ID: 485939



Open, exposed flowlines



Open, exposed flowlines

Inspection Photos
Location Name: Pan Am B 4,6,10,12
Spill ID: 485939



Groundwater within excavation

Groundwater within excavation

