

FORM INSP Rev X/20	State of Colorado Energy and Carbon Management Commission 1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109	 	Inspection Date: <u>10/30/2025</u> Submitted Date: <u>10/30/2025</u> Document Number: <u>719000830</u>
FIELD INSPECTION FORM			

Loc ID 333338 Inspector Name: GARCIA, CHARLES On-Site Inspection 2A Doc Num: _____

Operator Information:

ECMC Operator Number: 10755

Name of Operator: MORNINGSTAR OPERATING LLC

Address: 400 W 7TH ST

City: FORT WORTH State: TX Zip: 76102

Status Summary:

THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

14 Number of Comments
2 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM
 PREVIOUS INSPECTIONS THAT HAVE NOT
 BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
Kittinger, Eric		ekittinger@mspartners.com	Principal Agent

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
261584	WELL	PR	02/09/2004	CBM	007-06185	SWANEMYR 32-6 1-1	PR

General Comment:

[Inspection Report Summary](#)
 On 10/30/25 I Inspector Charles Garcia conducted an on-site inspection.
 Location: SWANEMYR 32-6 #1-1, 32-6 #1-2, 32-6 #1-3
 Operator: MORNINGSTAR OPERATING LLC
 API#: 007-06185
 County: ARCHULETA

Location

Overall Good:

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	PRODUCED WATER TANKS		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	LOCATION SIGNS		
Corrective Action:			Date:

Emergency Contact Number:			
Comment:	505-333-4869 911 EMERGENCY		
Corrective Action:			Date:

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	PUMP JACK		
Comment:	6FT CHAINLINK		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	6FT CHAIN LINK CATTLE PANELS		
Corrective Action:			Date:

Equipment:			corrective date
Type: Ancillary equipment	# 4		
Comment:	ELECTRIC PANELS		
Corrective Action:			Date:
Type: Flow Line	# 3		
Comment:			
Corrective Action:			Date:
Type: Other	# 3		
Comment:	WELLHEADS		
Corrective Action:			Date:
Type: Bird Protectors	# 5		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 3		

Comment:			
Corrective Action:			Date:
Type: Vertical Heated Separator	# 3		
Comment:			
Corrective Action:			Date:
Type: Pump Jack	# 2		
Comment:	PUMPJACKS APPER TO BE OUT OF SERVICE		
Corrective Action:			Date:
Type: Ancillary equipment	# 2		
Comment:	TELEMETRY EQUIPMENT		
Corrective Action:			Date:
Type: Other	# 3		
Comment:	METER HOUSES CALIBRATION IN COMPLIANCE		
Corrective Action:			Date:
Type: Bradenhead	# 3		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 3		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 3		
Comment:	CHEMICAL INJECTION COTAINERS WITH SPILL PREVENTION 2 CONTAINERS HAVE SUN DAMAGED LABELS AND NOT LEGIBLE		
Corrective Action:	Install sign or correct sign per rule 605		Date: 11/06/2025

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	400 BBLS	PBV STEEL		37.042900,-107.446200
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:	BERM HOLDING STORM WATER SEE LOCATION PIVTURES			
Corrective Action:	"Maintain adequate freeboard in spill prevention to prevent overflow. Fluid is discolored and may have some product mixed in, fluid should be disposed as waste in approved manner for type of chemical used			Date: 11/06/2025

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 261584 Type: WELL API Number: 007-06185 Status: PR Insp. Status: PR

Producing Well

Comment:

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 09/10/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
719000831	LOCATION PICTURES	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7309889