

FORM INSP Rev X/20	State of Colorado Energy and Carbon Management Commission 1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109	 	Inspection Date: <u>10/30/2025</u> Submitted Date: <u>10/30/2025</u> Document Number: <u>719000826</u>
FIELD INSPECTION FORM			

Loc ID 320878 Inspector Name: GARCIA, CHARLES On-Site Inspection 2A Doc Num: _____

Status Summary:

THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

11 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

Operator Information:

ECMC Operator Number: 10755
 Name of Operator: MORNINGSTAR OPERATING LLC
 Address: 400 W 7TH ST
 City: FORT WORTH State: TX Zip: 76102

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
Kittinger, Eric		ekittinger@mspartners.com	Principal Agent

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
265863	WELL	PR	03/08/2013	CBM	007-06196	DUNGAN 32-5 5-1	PR
374711	WELL	PR	09/01/2021	CBM	007-06279	CANDELARIA 32-5 8-3	PR

General Comment:

[Inspection Report Summary](#)
 On 10/30/25 | Inspector Charles Garcia conducted an on-site inspection.
 Location: CANDELARIA 32-5 #8-3, DUNGAN32-5 #5-1
 Operator: MORNINGSTAR OPERATING LLC
 API#: 007-06196 API#06279
 County: ARCHULETA

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	LOCATION SIGNS		
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:	PRODUCED WATER TANKS		
Corrective Action:			Date:

Emergency Contact Number:

Comment: 505-333-4869
911 EMERGENCY

Corrective Action: _____ Date: _____

Overall Good:

Spills:

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: _____

Multiple Spills and Releases?

Fencing/:

Type	PUMP JACK		
Comment:	6FT CHAIN LINK		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	6FT CHAIN LINK		
Corrective Action:			Date:

Equipment:

Type			corrective date
Type: Pump Jack	# 2		
Comment:			
Corrective Action:			Date:
Type: Pig Station	# 1		
Comment:			
Corrective Action:			Date:
Type: Vertical Heated Separator	# 3		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 2		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 2		

Comment:			
Corrective Action:			Date:
Type: Other	# 2		
Comment:	WELLHEADS		
Corrective Action:			Date:
Type: Ancillary equipment	# 8		
Comment:	5 ELECTRIC PANELS 2 TELEMETRY EQUIPMENT		
Corrective Action:			Date:
Type: Prime Mover	# 2		
Comment:	ELECTRIC		
Corrective Action:			Date:
Type: Flow Line	# 2		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:			Date:
Type: Other	# 3		
Comment:	METER HOUSES CALIBRATION IN COMPLIANCE		
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	400 BBLs	PBV STEEL		37.042200,-107.419600
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 265863 Type: WELL API Number: 007-06196 Status: PR Insp. Status: PR

Producing Well

Comment:	<input type="text"/>	
Corrective Action:	<input type="text"/>	Date: <input type="text"/>

BradenHead

Date of Last Brhd Test: 09/03/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment:

Corrective Action: Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 374711 Type: WELL API Number: 007-06279 Status: PR Insp. Status: PR

Producing Well

Comment:	<input type="text"/>	
Corrective Action:	<input type="text"/>	Date: <input type="text"/>

BradenHead

Date of Last Brhd Test: 09/03/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 123 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment:

Corrective Action: Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
719000827	LOCATION PICTURES	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7309888