

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/22/2025

Submitted Date:

10/24/2025

Document Number:

700300849

**FIELD INSPECTION FORM**

Loc ID 325806 Inspector Name: LABOWSKIE, STEVE On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 10749  
Name of Operator: SIMCOE LLC  
Address: 1199 MAIN AVE SUITE 101  
City: DURANGO State: CO Zip: 81301

**Findings:**

- 8 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
, General		sjninspections@ikavenergy.com	<a href="#">All Inspections</a>
Kosola, Jason		jason.kosola@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
215406	WELL	PR	04/15/1989	CBM	067-07011	HOTTER A 1	PR

**General Comment:**

[Follow-up inspection by SW Compliance Supervisor Steve labowskie to FIR doc#700300807.](#)  
[Buired vessel inventoried in 2019 inspection doc# 687905406 has been removed, no Form 27 in well file per Rule 913.c](#)

Location					
Overall Good: <input type="checkbox"/>					
<b>Signs/Marker:</b>					
Type	WELLHEAD				
Comment:					
Corrective Action:					Date:
Emergency Contact Number:					
Comment:					Date:
Corrective Action:					Date: _____
<b>Good Housekeeping:</b>					
Type	UNUSED EQUIPMENT				
Comment:	equipment not in use observed in previous inspection is no longer present				
Corrective Action:					Date:
Type	DEBRIS				
Comment:	Debris observed in previous inspection is no longer present.				
Corrective Action:					Date:
Type	OTHER				
Comment:	Appears coorrective action from previous inspection doc# 700300803 has been preformed. Area around compressor appears mostly cleaned up except right at edge of base of skid, appears that some lubricating oils may have seeped underneath, see photo				
Corrective Action:					Date:
Overall Good: <input type="checkbox"/>					
<b>Spills:</b>					
Type	Area	Volume			
In Containment: No _____					
Comment: <span style="border: 1px solid black; display: inline-block; width: 600px; height: 15px;"></span>					
<input type="checkbox"/> Multiple Spills and Releases?					
<b>Equipment:</b>					
					corrective date
Type: Compressor	# 1				
Comment:	Compressor skid is free oif lube oil anbd not overflowing porom recent precipitation. No physical modifications or improvements have been made.				
Corrective Action:					Date:
<b>Tanks and Berms:</b>					
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	0	OTHER	PBV STEEL		,
Comment:	Buried vessel and earthen containment documented in doc# 674602032 are longer present				
Corrective Action:	Re-submit Form 27 or schedule sampling required for buried vessel removal and closure required by rule 913.c				Date: <u>01/02/2026</u>
<b>Paint</b>					
Condition					

Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:					Date: <input style="width: 100px;" type="text"/>

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date: <input style="width: 100px;" type="text"/>

**Flaring:**

Type		
Comment:		
Corrective Action:		Date: <input style="width: 100px;" type="text"/>

**Inspected Facilities**

Facility ID: 215406 Type: WELL API Number: 067-07011 Status: PR Insp. Status: PR

**BradenHead**

Date of Last Brhd Test: 06/08/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: 0

Comment: last Form 17 6/25/25 0 pressure

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass					
Gravel	Pass					

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404405687	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7297234">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7297234</a>
700300859	Well sign	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7297224">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7297224</a>
700300860	south side of compressor skid	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7297225">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7297225</a>
700300861	north side of compressor skid	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7297226">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7297226</a>
700300862	wellhead area	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7297227">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7297227</a>
700300863	general area where buried tank and berms were	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7297228">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7297228</a>