

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/03/2025

Submitted Date:

10/24/2025

Document Number:

701104277

FIELD INSPECTION FORM

Loc ID 335102 Inspector Name: LONGWORTH, MIKE On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10844
Name of Operator: QB ENERGY OPERATING LLC
Address: 1001 17TH STREET SUITE 1600
City: DENVER State: CO Zip: 80202

Findings:

- 2 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		ecmc.inspections@qb-energy.com	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
272024	WELL	PR	12/01/2004	GW	045-09998	GMR 34-3 (B34NW)	EG
272025	WELL	PR	11/23/2004	GW	045-09999	GMR 34-2 (B34NW)	EG
272026	WELL	PR	01/01/2024	GW	045-10000	GMR 34-1B (B34NW)	EG
272027	WELL	PR	11/29/2004	GW	045-10001	GMR 34-2B (B34NW)	EG
491149	SPILL OR RELEASE	AC	08/25/2025		-	B34NW Separator Release	EG

General Comment:

Flowline Integrity Inspection and Tank Integrity Inspection
Spill/Release Id. # 491149
EXcavations of risers and dumplines behind separtors.
Multiple out of service risers with either no OSSLAT tag or broken off tags.

Location

Overall Good:

Signs/Marker:			
Type	OTHER		
Comment:	Multiple out of service risers with either no OSSLAT tag or broken off tags.		
Corrective Action:	Install/replace OSSLAT tags.	Date:	10/31/2025

Emergency Contact Number:			
Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>		Date: _____

Overall Good:

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No			
Comment:	<input type="text"/>		
Corrective Action:		Date:	

Flaring:

Type		
Comment:	<input type="text"/>	
Corrective Action:		Date:

Inspected Facilities

Facility ID: 272024 Type: WELL API Number: 045-09998 Status: PR Insp. Status: EG

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 272025 Type: WELL API Number: 045-09999 Status: PR Insp. Status: EG

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 272026 Type: WELL API Number: 045-10000 Status: PR Insp. Status: EG

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 272027 Type: WELL API Number: 045-10001 Status: PR Insp. Status: EG

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 491149 Type: SPILL OR API Number: - Status: AC Insp. Status: EG

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404403933	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7295510
701104288	Flowline integrity inspection 701104277 photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7295489