

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/06/2025

Submitted Date:

10/24/2025

Document Number:

701104289

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: LONGWORTH, MIKE On-Site Inspection
335648 _____ 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10844
Name of Operator: QB ENERGY OPERATING LLC
Address: 1001 17TH STREET SUITE 1600
City: DENVER State: CO Zip: 80202

Findings:

- 2 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
		ecmc.inspections@qb-energy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
283955	WELL	PR	05/15/2008	GW	045-12041	N. PARACHUTE WF11B K22 596	EG

General Comment:

Flowline Integrity Inspection of Spill/Release Id. # 491480
Corrective action comments from F19 Report Doc # 404369516
The release was caused by external corrosion of the carbon steel flowline, which was placed on a large rock.
The flowline was repaired and rock guard was installed along the flowline to prevent reoccurrence of the incident.

2-1" risers with hose that is run into a secondary containment of chemical tote on south east edge of location. Purpose of this line is not understood to ECMC staff Mike Longworth.
Communicate with Mike Longworth to explain what this line is being used for.
Evaluate use of line and best management practices of line.
CA Date 10/31/2025

Inspected Facilities

Facility ID: 283955 Type: WELL API Number: 045-12041 Status: PR Insp. Status: EG

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404404406	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7296056
701104291	Flowline integrity inspection 701104289 photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7296050