

Final Reclamation and Stormwater Inspection

October 28, 2025

Operator: WESCO OPERATING INC - 95520

Location ID: 316929

Well Name: LINKER #1

Inspection Document #: 718601099

Washington County, CO

Anthony Dunnam
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: LINKER #1
Location ID: 316929



Photo 1. Looking east across the entrance of the access road and tank battery. No oil and gas equipment remains on the location. This area appears to have less crop germination than surrounding area.



Photo 2. Looking north across the west side of the tank battery including entrance area. See photo 1 comments.



Inspection Photos
Location Name: LINKER #1
Location ID: 316929



Photo 3. Looking east across the former pit/ evaporation pond area. This area does not appear to be contoured to surrounding terrain. Depressions, peaks and berms are visible in the pit area and it appears that farming equipment may have had trouble navigating this area.



Photo 4. west across the pit area from the southeast corner. Uneven terrain and lower germination than the surrounding cropland.



Inspection Photos
Location Name: LINKER #1
Location ID: 316929



Photo 5. Picture taken west of the evaporation pond area looking east across the pit area. There appears to be black stained soil chunks (red circle). This area also had a strong hydrocarbon smell.



Photo 6. Looking east down the former access road towards the wellhead. Stormwater erosion is present along the former path of the access road.



Inspection Photos
Location Name: LINKER #1
Location ID: 316929



Photo 7. Looking west along the access road from the former wellhead area. Stormwater erosion is only present on the former access road portion of the slope (red circle).



Photo 8. Looking east across the wellbore area. No oil and gas equipment remains. The well bore area appears reflective of the surrounding crop area.

Inspection Photos
Location Name: LINKER #1
Location ID: 316929



Photo 9. Looking south from the wellbore. See photo 8 comments.



Photo 10. Looking west from the wellbore. See photo 8 comments.

Inspection Photos
Location Name: LINKER #1
Location ID: 316929



Photo 11. Looking north from the wellbore. See photo 8 comments.



Photo 12. Google earth aerial imagery taken 09/17/2012. Illustrating footprint of the tank battery, access road and well location while active.

