

# Inspection Photos

ID: 321591

Operator: **CITATION OIL & GAS CORP**

Inspection Date: 10/21/2025

County: Cheyenne



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos



**Photo 1.** Facing southeast at the location. There is insufficient vegetation germination and additional reclamation will need to be completed.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

ID: 321591 | Date: 10/21/2025

## Inspection Photos



**Photo 2.** Facing southeast at the location. There is insufficient vegetation germination and additional reclamation will need to be completed. There is undesirable weeds (debris) along the fence line that needs to be removed.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

ID: 321591 | Date: 10/21/2025

## Inspection Photos



**Photo 3.** Facing northwest at the location. There is insufficient vegetation germination and additional reclamation will need to be completed.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

ID: 321591 | Date: 10/21/2025

## Inspection Photos



**Photo 4.** Facing northwest at the east side of the location. This area outside of the fence is bare of vegetation and needs to be reclaimed.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

ID: 321591 | Date: 10/21/2025

## Inspection Photos



**Photo 5.** Facing west at the location. There is insufficient vegetation germination and additional reclamation will need to be completed.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

ID: 321591 | Date: 10/21/2025

## Inspection Photos



**Photo 6.** Facing west. The fence has fallen over and needs maintenance.

