

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/30/2025

Submitted Date:

10/31/2025

Document Number:

717300568

FIELD INSPECTION FORM

Loc ID 330943 Inspector Name: Maclaren, Joe On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 47120
Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP
Address: P O BOX 173779
City: DENVER State: CO Zip: 80217-

Findings:

- 4 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
		ECMCInspections@Oxy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
256705	WELL	SI	03/01/2019	GW	123-19910	HSR CANNON FEDERAL 5-17A	PA
470300	TANK BATTERY	AC	12/19/2019		-	HSR Cannon Federal 5-17A battery	EG

General Comment:

ECMC Engineering Integrity Inspection; Flowline Inspection
Photos uploaded

Inspected Facilities

Facility ID: 256705 Type: WELL API Number: 123-19910 Status: SI Insp. Status: PA

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 470300 Type: TANK API Number: - Status: AC Insp. Status: EG

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
Well is plugged and abandoned (HSR Cannon 5-17A); ECMC form 42 notice of start of plugging operations doc #404239179 received on 06/12/2025. Wellhead flowline has been AIP; facility end is below grade/ sealed (tracer wire) & marked. The facility/ tank battery has been decommissioned; on location flowlines, tanks and equipment removed. ECMC form 42 notice of flowline abandonment completed doc #404361059 received 09/19/2025. Remediation work is in progress.	maclarej	10/31/2025
As outlined on ECMC form 19 spill report Doc #404400915 received on 10/24/2025: While conducting facility decommissioning activities at the former Cannon FD4& 5-17A facility, historically impacted soil was discovered beneath a former aboveground storage tank and a produced water vault. The volume of the release is unknown. The facility has been decommissioned.	maclarej	10/31/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/webblink/>) and search by document number:

Document Num	Description	URL
717300573	Facility decommissioned; excavations (NO FL's)	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7311648
717300574	Flowline 5-17A AIP below grade; signage	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7311649
717300575	Fenced excavations; OOS GMR	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7311650