

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/30/2025

Submitted Date:

11/02/2025

Document Number:

708907777

**FIELD INSPECTION FORM**

Loc ID 323967 Inspector Name: Smelser, Wayne On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 96850  
Name of Operator: TEP ROCKY MOUNTAIN LLC  
Address: 1058 COUNTY ROAD 215  
City: PARACHUTE State: CO Zip: 81635

**Findings:**

6 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
TEP		ECMCInspectionReports@flywheelenergy.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
467556	Domestic Tap	AC	09/16/2019		-	Domestic Tap 34NWSW	AC

**General Comment:**

[This is a Field Inspection/Audit of the scout card, related documents and the location.](#)

<b>Location</b>				
<b>Lease Road:</b>				
	Type Access			
	comment:			
	Corrective ActionL			Date:
Overall Good: <input type="checkbox"/>				
<b>Emergency Contact Number:</b>				
	Comment:	<input style="width: 80%;" type="text"/>		
	Corrective Action:	<input style="width: 80%;" type="text"/>		
Date: _____				
Overall Good: <input type="checkbox"/>				
<b>Spills:</b>				
Type	Area	Volume		
In Containment: No				
	Comment:	<input style="width: 80%;" type="text"/>		
<input type="checkbox"/> Multiple Spills and Releases?				
<b>Fencing/:</b>				
	Type OTHER			
	Comment: Domestic tap - pipe rail fence			
	Corrective Action:			Date:
<b>Equipment:</b>				
				corrective date
Type: Other		# 1		
	Comment: Domestic tap			
	Corrective Action:			Date:
<b>Venting:</b>				
	Yes/No NO			
	Comment:			
	Corrective Action:			Date:
<b>Flaring:</b>				
Type				
	Comment:			
	Corrective Action:			Date:

**Inspected Facilities**

Facility ID: 467556 Type: Domestic Tap API Number: - Status: AC Insp. Status: AC

**Producing Well**

Comment: While there, I observed the domestic tap is derived from TEP's sales line. The pressure is regulated by a Fisher Big Joe regulator. Following the big joe there's a Norriseal-Wellmark 2002PR regulator. Following the regulator there's a fluid knock out equipped with a PRV, following the knock out there's an in line odorizer. Fittings appear to be adequately sized.

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**ECMC Comments**

Comment	User	Date
<p><a href="#">CECMC Inspection/Audit Report Summary</a>                      On 10/30/2025 at approximately 14:12 hours, I, Compliance Specialist, Wayne Smelser Conducted a domestic tap inspection/audit at TEP ROCKY MOUNTAIN LLC Domestic Tap 34NWSW                      Location # 323967 Facility # 467556 in Garfield County Colorado.                      While there, I observed the domestic tap is derived from TEP sales line.                      Domestic tap inspection/audit only</p> <p><a href="#">This is a summary of inspection/audit report</a></p>	smelserw	11/02/2025

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708907778	Inspection/Audit 708907777 photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7313739">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7313739</a>