

<b>FORM</b> <b>INSP</b> Rev X/20	<b>State of Colorado</b> <b>Energy and Carbon Management Commission</b> 1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109	 	Inspection Date: <u>11/04/2025</u> Submitted Date: <u>11/04/2025</u> Document Number: <u>719000886</u>
<b>FIELD INSPECTION FORM</b>			

Loc ID \_\_\_\_\_ Inspector Name: GARCIA, CHARLES On-Site Inspection   
 326137 \_\_\_\_\_ 2A Doc Num: \_\_\_\_\_

**Operator Information:**

ECMC Operator Number: 10133

Name of Operator: HILCORP ENERGY COMPANY

Address: P O BOX 61229

City: HOUSTON State: TX Zip: 77208

**Status Summary:**

THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

9 Number of Comments  
1 Number of Corrective Actions  
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM  
 PREVIOUS INSPECTIONS THAT HAVE NOT  
 BEEN ADDRESSED ARE STILL APPLICABLE

**Contact Information:**

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
, General		FarmingtonRegulatoryTechs@hilcorp.com	SJB inspect

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
215932	WELL	PR	08/01/1991	CBM	067-07537	HUBER-JEFFRIES 1-5	PR
476720	Domestic Tap	AC	06/03/2020		-	Domestic Tap 5NESE	AC

**General Comment:**

[Inspection Report Summary](#)  
 On 11/4/25 | Inspector Charles Garcia conducted an on-site inspection.  
 Location: HUBER-JEFFRIES 1-5  
 API# 067-07537  
 Operator: HILLCORP ENERGY COMPANY  
 County: LaPlata

**Location**

Overall Good:

<b>Signs/Marker:</b>			
Type	OTHER		
Comment:	LOCATION SIGN AT ENTERANCE		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	24 Hr #970-247-6916 Emergency #911	Date:	
Corrective Action:		Date:	

Overall Good:

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	PUMP JACK		
Comment:	SOUND WALLS		
Corrective Action:		Date:	
Type	LOCATION		
Comment:	BARBWIRE		
Corrective Action:		Date:	

<b>Equipment:</b>		corrective date
Type: Deadman # & Marked	# 4	
Comment:		
Corrective Action:		Date:
Type: Pump Jack	# 1	
Comment:		
Corrective Action:		Date:
Type: Bradenhead	# 1	
Comment:		
Corrective Action:		Date:
Type: Other	# 1	
Comment:	WELLHEAD	
Corrective Action:		Date:
Type: Vertical Heated Separator	# 1	
Comment:		
Corrective Action:		Date:
Type: Gas Meter Run	# 1	

Comment:	CALIBRATION IN COMPLIANCE		Date:	
Corrective Action:			Date:	
Type: Flow Line	# 1			
Comment:			Date:	
Corrective Action:			Date:	
Type: Bird Protectors	# 1			
Comment:			Date:	
Corrective Action:			Date:	
Type: Prime Mover	# 1			
Comment:	GAS ENGINE HAS OIL LEAK AND STARTING TO FILL SKID WITH OIL SEE LOCATION PICTURES		Date:	
Corrective Action:	MAINTAIN ENGINE RULE 608.e		Date:	11/18/2025

**Venting:**

Yes/No		Date:	
Comment:			
Corrective Action:			Date:

**Flaring:**

Type		Date:	
Comment:			
Corrective Action:			Date:



**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
719000887	LOCATION PICTURES	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7317358">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7317358</a>