

FORM  
INSPRev  
X/20

# State of Colorado Energy and Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/05/2025

Submitted Date:

11/05/2025

Document Number:

713302322

## FIELD INSPECTION FORM

Loc ID 318221 Inspector Name: Kester, Michael On-Site Inspection  2A Doc Num: \_\_\_\_\_

### Status Summary:

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

### Findings:

9 Number of Comments

0 Number of Corrective Actions

Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

### Operator Information:

ECMC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1700 LINCOLN ST STE 4550

City: DENVER State: CO Zip: 80203

### Contact Information:

Contact Name	Phone	Email	Comment
, KPK	303-825-4822	cogcc@kpk.com	<a href="#">all inspections</a>

### Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
240906	WELL	PR	11/01/2021	OW	123-08694	ELKHORN COMPANY B 5	PR

### General Comment:

[well site inspection](#)

**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:	good		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:			
Corrective Action:		Date:	

Overall Good:

**Spills:**

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	PUMP JACK		
Comment:	safety guards		
Corrective Action:		Date:	

**Equipment:**

Type	#	Comment	Corrective Action	Date	corrective date
Type: Pump Jack	# 1				
Comment:					
Corrective Action:				Date:	
Type: Bradenhead	# 1				
Comment:		piped to surface			
Corrective Action:				Date:	
Type: Ancillary equipment	# 4				
Comment:		electric/automation panels			
Corrective Action:				Date:	
Type: Prime Mover	# 1				
Comment:		electric			
Corrective Action:				Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			

Corrective Action:

Date:

**Inspected Facilities**

Facility ID: 240906 Type: WELL API Number: 123-08694 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR, Valves appeared to be open at time of inspection

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 01/29/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**ECMC Comments**

Comment	User	Date
<u>Audit of scout card and related documents</u> <u>Routine inspection</u>	kesterm	11/05/2025
<u>This inspection does not nullify any orders or NOAV from the ECMC</u>		

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713302323	site pic	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7319563">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7319563</a>