

Inspection Photos

10/29/2025

Operator: SWN Production Company LLC

#10396

Location ID: 313134

Inspection Doc: 719200383

Moffatt County, CO

Emily Gaasche
NW Reclamation Specialist
ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: SWN Production Company LLC #10396

Location ID: 313134



Photo 1: Photos showing an overview of the location looking north and south, respectively.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: SWN Production Company LLC #10396

Location ID: 313134



Photo 2: Photos showing an overview of the location looking east and west, respectively.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: SWN Production Company LLC #10396

Location ID: 313134



Photo 3: Photos showing an example of Scotch thistle (left), a List B noxious weed and knapweed, also a noxious weed, that is present throughout the location. It does not appear as though weeds have been managed in 2025.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: SWN Production Company LLC #10396

Location ID: 313134



Photo 4: Photo left showing an infestation of knapweed, occurring on the northeastern portion of the location. Photo right showing new Scotch thistle growth at the location. It does not appear as though weeds have been managed in 2025.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: SWN Production Company LLC #10396

Location ID: 313134



Photo 5: Photos showing examples of the southern portion of the location. Areas remain predominantly bare and uniform vegetation is not evident. Erosion and rilling is occurring.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: SWN Production Company LLC #10396

Location ID: 313134



Photo 6: Photos showing examples of the southern portion of the location. Areas remain predominantly bare and uniform vegetation is not evident. Erosion and rilling is occurring.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: SWN Production Company LLC #10396

Location ID: 313134



Photo 7: Photos showing a sediment trap on the southeastern end of the location has not been recontoured or reclaimed. An infestation of Scotch thistle is present (yellow arrow).



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: SWN Production Company LLC #10396

Location ID: 313134



Photo 8: Photo showing a soil stockpile/berm remaining on the location. Location has not been properly contoured, and soils replaced. Soils are predominantly bare; BMPs to protect the stockpiled soils from erosion, degradation, weed establishment, as well as BMPs to minimize sediment transport are missing or insufficient.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: SWN Production Company LLC #10396

Location ID: 313134



Photo 9: Photos showing the northeastern access road to the location remains unreclaimed. Gravel and compaction is evident.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: SWN Production Company LLC #10396

Location ID: 313134



Photo 10: Photos showing erosion, rilling and sediment migration occurring on the northeastern access road. Ongoing stormwater maintenance is necessary until the location receives a passing final reclamation inspection.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: SWN Production Company LLC #10396

Location ID: 313134



Photo 11: Photo showing utility equipment remains at the location and requires removal.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: SWN Production Company LLC #10396

Location ID: 313134



Photo 12: Photos showing the western access road that remains unreclaimed. Gravel and compaction is evident.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: SWN Production Company LLC #10396

Location ID: 313134



Photo 13: Photos showing an example of the reference area, located to the south of the location. Reference areas are characterized by big sagebrush shrublands, and big sagebrush is dominant.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: SWN Production Company LLC #10396

Location ID: 313134



Photo 14: Google Earth aerial imagery. Top photo dated 2023; bottom 1994. Yellow lines represent access roads that existed prior to Oil and Gas disturbances. Red lines represent access roads constructed to Oil and Gas Locations subject to 1004 final reclamation requirements. Access road to the Walker 3-1 did not pre-exist the location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources