

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/29/2025

Submitted Date:

10/30/2025

Document Number:

717701769

FIELD INSPECTION FORM

Loc ID 453242 Inspector Name: Burns, Adam On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 47120
Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP
Address: P O BOX 173779
City: DENVER State: CO Zip: 80217-

Findings:

- 7 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		ECMCInspections@Oxy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
453241	WELL	SI	03/01/2025	OW	123-46001	Mustang V41-34-33XRLNB	SI
482236	TANK BATTERY	AC	05/27/2022		-	Mustang 42-34 Tank Battery	SI

General Comment:

This is a follow up to FIRR document #404399140. Some CA's have been corrected one still hasnt been corrected.

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type

UNUSED EQUIPMENT

Comment:

Unused Equipment ECD needs to be removed for good housekeeping. See attached photo

Corrective Action:

Comply with Rule 606.

Date: 10/10/2025

Overall Good:

Spills:

Type

Area

Volume

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

corrective date

Type: Emission Control Device

#

Comment:

1 is unused equipment

Corrective Action:

Date:

Venting:

Yes/No

NO

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected Facilities

Facility ID: 453241 Type: WELL API Number: 123-46001 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: SI

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 07/21/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 87 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 482236 Type: TANK API Number: - Status: AC Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: SI

Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
<p>ECMC Audit Report Summary</p> <p>On Wednesday, October 29, 2025, at approximately 11:30 PM, Inspector Adam Burns conducted an on-site audit to FIRR document #404399140 at the following location: Some CA's were correct 1 CA still not addressed Location: Mustang 42-34 Operator: Oxy Location ID #453242 County: Weld During the audit, the following possible compliance issues were identified: Unused Equipment ECD needs to be removed for good housekeeping. Comply with Rule 606. CA date of 10/10/25 A follow-up audit is scheduled to ensure that the compliance issues have been rectified to comply with ECMC rules. Please note that any corrective actions from previous audits that have not been addressed remain applicable.</p>	burnsa	10/30/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404416913	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7309954
717701770	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7309952