

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/29/2025

Submitted Date:

10/30/2025

Document Number:

717701774

FIELD INSPECTION FORM

Loc ID 422497 Inspector Name: Burns, Adam On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 47120
Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP
Address: P O BOX 173779
City: DENVER State: CO Zip: 80217-

Findings:

- 7 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		ECMCInspections@Oxy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
422517	WELL	SI	12/01/2023	OW	123-33295	FRENCH LAKE 4-63-36 1H	SI
482284	TANK BATTERY	AC	06/07/2022		-	French Lake 4-63-36 1B Tank Battery	SI

General Comment:

[This is a follow up to FIRR document #404398766. Some CA's have been corrected. Pumping unit is still unused equipment.](#)

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type

UNUSED EQUIPMENT

Comment:

Unused Pumping unit "no prime mover" and other unused equipment around the well needs to be removed for good housekeeping. See attached photos

Corrective Action:

Comply with Rule 606

Date: 12/31/2025

Overall Good:

Spills:

Type

Area

Volume

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

corrective date

Type: VRU

1

Comment:

VRU on location. was not on location from prior inspection

Corrective Action:

Date:

Venting:

Yes/No

NO

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected Facilities

Facility ID: 422517 Type: WELL API Number: 123-33295 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____
 Comment:
 Corrective Action: Date: _____

BradenHead

Date of Last Brhd Test: 10/01/2025 Annual Brhd Completed? Yes
 Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONE
 End Surf Csg Pressure: 0
 Comment:
 Corrective Action: Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12
 Facility ID: 482284 Type: TANK API Number: - Status: AC Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____
 Comment:
 Corrective Action: Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
<p>ECMC Audit Report Summary</p> <p>On Wednesday, October 29, 2025, at approximately 10:48 AM, Inspector Adam Burns conducted an on-site audit to FIRR document #404398766 to the following location: Some CA's were addressed Location: French Lake 3-63-36 1H Operator: OXY Location ID #422497 County: Weld During the audit, the following possible compliance issues were identified: Unused Pumping unit "no prime mover" and other unused equipment around the well needs to be removed for good housekeeping. Comply with Rule 606. CA date of 12/31/25 A follow-up audit is scheduled to ensure that the compliance issues have been rectified to comply with ECMC rules. Please note that any corrective actions from previous audits that have not been addressed remain applicable.</p>	burnsa	10/30/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404416914	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7309955
717701775	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7309953