

<b>FORM</b> <b>INSP</b> Rev X/20	<b>State of Colorado</b> <b>Energy and Carbon Management Commission</b> 1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109	 	Inspection Date: <u>10/30/2025</u> Submitted Date: <u>10/30/2025</u> Document Number: <u>719000830</u>
<b>FIELD INSPECTION FORM</b>			

Loc ID 333338      Inspector Name: GARCIA, CHARLES      On-Site Inspection       2A Doc Num: \_\_\_\_\_

**Status Summary:**

THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

14 Number of Comments  
2 Number of Corrective Actions  
 Corrective Action Response Requested

**Operator Information:**

ECMC Operator Number: 10755  
 Name of Operator: MORNINGSTAR OPERATING LLC  
 Address: 400 W 7TH ST  
 City: FORT WORTH      State: TX      Zip: 76102

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
Kittinger, Eric		ekittinger@mspartners.com	Principal Agent

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
261584	WELL	PR	02/09/2004	CBM	007-06185	SWANEMYR 32-6 1-1	PR

**General Comment:**

[Inspection Report Summary](#)  
 On 10/30/25 I Inspector Charles Garcia conducted an on-site inspection.  
 Location: SWANEMYR 32-6 #1-1, 32-6 #1-2, 32-6 #1-3  
 Operator: MORNINGSTAR OPERATING LLC  
 API#: 007-06185  
 County: ARCHULETA

**Location**

Overall Good:

<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:	PRODUCED WATER TANKS		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	LOCATION SIGNS		
Corrective Action:			Date:

Emergency Contact Number:			
Comment:	505-333-4869 911 EMERGENCY		
Corrective Action:			Date:

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	PUMP JACK		
Comment:	6FT CHAINLINK		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	6FT CHAIN LINK CATTLE PANELS		
Corrective Action:			Date:

<b>Equipment:</b>			corrective date
Type: Ancillary equipment	# 4		
Comment:	ELECTRIC PANELS		
Corrective Action:			Date:
Type: Flow Line	# 3		
Comment:			
Corrective Action:			Date:
Type: Other	# 3		
Comment:	WELLHEADS		
Corrective Action:			Date:
Type: Bird Protectors	# 5		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 3		

Comment:		
Corrective Action:		Date:
Type: Vertical Heated Separator	# 3	
Comment:		
Corrective Action:		Date:
Type: Pump Jack	# 2	
Comment:	PUMPJACKS APPER TO BE OUT OF SERVICE	
Corrective Action:		Date:
Type: Ancillary equipment	# 2	
Comment:	TELEMETRY EQUIPMENT	
Corrective Action:		Date:
Type: Other	# 3	
Comment:	METER HOUSES CALIBRATION IN COMPLIANCE	
Corrective Action:		Date:
Type: Bradenhead	# 3	
Comment:		
Corrective Action:		Date:
Type: Gas Meter Run	# 3	
Comment:		
Corrective Action:		Date:
Type: Ancillary equipment	# 3	
Comment:	CHEMICAL INJECTION COTAINERS WITH SPILL PREVENTION 2 CONTAINERS HAVE SUN DAMAGED LABELS AND NOT LEGIBLE	
Corrective Action:	Install sign or correct sign per rule 605	Date: 11/06/2025

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	400 BBLS	PBV STEEL		37.042900,-107.446200
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:	BERM HOLDING STORM WATER SEE LOCATION PIVTURES			
Corrective Action:	"Maintain adequate freeboard in spill prevention to prevent overflow. Fluid is discolored and may have some product mixed in, fluid should be disposed as waste in approved manner for type of chemical used			Date: 11/06/2025

<b>Venting:</b>			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 261584 Type: WELL API Number: 007-06185 Status: PR Insp. Status: PR

**Producing Well**

Comment:

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 09/10/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404416877	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7309892">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7309892</a>
719000831	LOCATION PICTURES	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7309889">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7309889</a>