

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/30/2025

Submitted Date:

10/30/2025

Document Number:

719000839

**FIELD INSPECTION FORM**

Loc ID 334051 Inspector Name: GARCIA, CHARLES On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 10755  
Name of Operator: MORNINGSTAR OPERATING LLC  
Address: 400 W 7TH ST  
City: FORT WORTH State: TX Zip: 76102

**Findings:**

- 13 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Kittinger, Eric		ekittinger@mspartners.com	Principal Agent
Labowskie, Steve		steve.labowskie@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
277576	WELL	PR	05/11/2005	CBM	007-06212	SWANEMYR 32-6 1-2	PR
293817	WELL	PR	11/30/2007	CBM	007-06240	SWANEMYR 32-6 1-3	PR

**General Comment:**

Inspection Report Summary  
On 10/30/25 I Inspector Charles Garcia conducted an on-site inspection.  
Location: SWANEMYR 32-6 #1-1, 32-6 #1-2, 32-6 #1-3  
Operator: MORNINGSTAR OPERATING LLC  
API#: 007-06185 API#007-06212 API#007-06240  
County: ARCHULETA

**Location**

Overall Good:

<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:	PRODUCED WATER TANKS		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	LOCATION SIGNS		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	505-333-4869 911 EMERGENCY		
Corrective Action:		Date:	

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	PUMP JACK		
Comment:	6FT CHAIN LINK		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	6FT CHAIN LINK CATTLE PANELS		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Bird Protectors	# 5		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 3		
Comment:			
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 3		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 3		
Comment:			
Corrective Action:		Date:	

Type: Other	# 3	
Comment:	METER HOUSES CALIBRATION IN COMPLIANCE	
Corrective Action:		Date:
Type: Ancillary equipment	# 4	
Comment:	ELECTRIC PANELS	
Corrective Action:		Date:
Type: Gas Meter Run	# 3	
Comment:		
Corrective Action:		Date:
Type: Bradenhead	# 3	
Comment:		
Corrective Action:		Date:
Type: Flow Line	# 3	
Comment:		
Corrective Action:		Date:
Type: Pump Jack	# 2	
Comment:	PUMPJACKS APPER TO BE OUT OF SERVICE	
Corrective Action:		Date:
Type: Other	# 3	
Comment:	WELLHEADS	
Corrective Action:		Date:
Type: Ancillary equipment	# 3	
Comment:	CHEMICAL INJECTION COTAINERS WITH SPILL PREVENTION 2 CONTAINERS HAVE SUN DAMAGED LABELS AND NOT LEGIBLE	
Corrective Action:	Install sign or correct sign per rule 605	Date: 11/06/2025

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	400 BBLs	PBV STEEL		37.042900,-107.446200
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficient	Adequate
Comment:	BERM HOLDING STORM WATER SEE LOCATION PIVTURES			
Corrective Action:	Maintain adequate freeboard in spill prevention to prevent overflow. Fluid is discolored and may have some product mixed in, fluid should be disposed as waste in approved manner for type of chemical used			Date: 11/06/2025

<b>Venting:</b>			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 277576 Type: WELL API Number: 007-06212 Status: PR Insp. Status: PR

**Producing Well**

Comment:

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 08/28/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 37 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 293817 Type: WELL API Number: 007-06240 Status: PR Insp. Status: PR

**Producing Well**

Comment:

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 09/10/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404416880	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7309894">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7309894</a>
719000840	LOCATION PICTURES	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7309887">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7309887</a>