

WGS84  
±10ft

40.24400, -104.63380

m  
±3m


1455

°T  
±15

W279



Former Aristocrat PC H11-19D Tank Battery. Surface appears to have been re-scraped/levelled recently.



Aristocrat PC H11-19D  
© 30-Oct-25 13:22:18  
ECMC Environmental Inspection

Looking at the Former Aristocrat PC H11-19D Tank Battery and approximate location of Spill ID 491220. Surface appears to have been re-scraped/levelled recently; however, the excavation at the spill location remains backfilled to a grade above that of the surrounding location.

Pump at the adjacent irrigation pond southwest of the spill location.

Irrigation pond

Approximate area backfilled above grade


Approximate location of Spill ID 491220

**ECMC**  
**Environmental**  
**Field Inspection**



Aristocrat PC H11-19D  
e 30-Oct-25 13:22:22  
ECMC Environmental Inspection

Looking at the Former Aristocrat PC H11-19D Tank Battery and approximate location of Spill ID 491220. Surface appears to have been re-scraped/levelled recently; however, the excavation at the spill location remains backfilled to a grade above that of the surrounding location.



Looking at the Former Aristocrat PC H11-19D Tank Battery and approximate location of Spill ID 491220. Surface appears to have been re-scraped/levelled recently; however, the excavation at the spill location remains backfilled to a grade above that of the surrounding location.

WGS84 40 24397 -104 63377 1455 NW286  
±16ft ±4m ±12



**ECMC**  
**Environmental**  
**Field Inspection**



Aristocrat PC H11-19D  
© 30-Oct-25 13:25:14  
ECMC Environmental Inspection

Pea gravel and soil used as backfill.