

Final Reclamation and Stormwater Inspection

October 29, 2025

Operator: IMPETRO RESOURCES LLC - 10690

Location ID: 316923

Well Name: STATE #1

Inspection Document #: 718601123

Washington County, CO

Anthony Dunnam
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: STATE #1
Location ID: 316923



Photo 1. Looking northwest across the former tank battery and equipment area. Equipment and tanks have been removed.



Photo 2. Looking northwest across the former storage tank area. Tanks have been removed. Wooden or cement foundation remains where the former blue open top tank was located.



Inspection Photos
Location Name: STATE #1
Location ID: 316923



Photo 3. Looking northwest across the storage tank area along the east side of the pit. Concrete rubble is present.



Photo 4. Looking west across the southernmost pit (ID 440212).



Inspection Photos
Location Name: STATE #1
Location ID: 316923



Oct 29, 2025
165° S
ECMC

Photo 5. Soil pile near pit ID 440212 does not have stormwater protection BMPs.



Oct 29, 2025
300° NW
ECMC

Photo 6. Looking west across pit #107648. It appears that equipment was removed from the south wall of this pit.



Inspection Photos
Location Name: STATE #1
Location ID: 316923



Photo 7. Looking east across pit #117577. Overflow pipe remains (red circle).



Photo 8. Looking south across the well location. Fence, spool and debris have been removed.

Inspection Photos
Location Name: STATE #1
Location ID: 316923



Oct 29, 2025
250° W
ECMC

Photo 9. Looking west across the well area. Cement pad and electric poles remain.



Oct 29, 2025
188° S
ECMC

Photo 10. Excavation around the wellhead is filled in. A pipe riser remains.

