

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/31/2025

Submitted Date:

10/31/2025

Document Number:

698708255

FIELD INSPECTION FORM

Loc ID 307896 Inspector Name: Serna, Abe On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10758
Name of Operator: OGRIS OPERATING LLC
Address: PO BOX 53467
City: MIDLAND State: TX Zip: 79710

Findings:

- 8 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Baca, Dave	719-846-4066	dbaca@ogrisop.com	
, Ogris	719-220-4041	gzeches@ogrisop.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
259238	WELL	PR	09/04/2005	CBM	071-07211	HILL RANCH 22-12 V	PR

General Comment:

"This is a field audit of the scout card, related documents and the location."

Location

Overall Good:

Signs/Marker:			
Type	OTHER		
Comment:	Well sign on meter house		
Corrective Action:			Date:

Emergency Contact Number:		
Comment:	<input type="text"/>	
Corrective Action:	<input type="text"/>	Date: _____

Good Housekeeping:			
Type	UNUSED EQUIPMENT		
Comment:	Engine skid in sound walls with no engine needs to be removed and engine on location with no skid needs to be removed		
Corrective Action:	Comply with rule 605		Date: 11/07/2025
Type	OTHER		
Comment:	Impacted soil around well head needs be be removed and hauled off also need to fix mechanical issue causing leak		
Corrective Action:	Comply with rule 605		Date: 11/07/2025

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:			corrective date
Type: Bradenhead	# 1		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:	CAL. REPORT INDICATES GAS METER HAS BEEN CALIBRATED WITHIN THE LAST YEAR.		
Corrective Action:			Date:
Type: Prime Mover	# 1		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:			
Corrective Action:			Date:
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:			Date:

Type: Vertical Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Progressive Cavity	# 1		
Comment:			
Corrective Action:			Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 259238 Type: WELL API Number: 071-07211 Status: PR Insp. Status: PR

Producing Well

Comment: [PR](#)

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 05/08/2024 Annual Brhd Completed? No

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment: [Submit files](#)

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches	Pass	Culverts	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Type: Produced Water Lined: NO Pit ID: Lat: Long:

Reference Point: _____ Other: _____ Length: _____ Width: _____

Lining:

Liner Type: _____ Liner Condition: _____

Comment:

Corrective

Date: _____

Fencing:

Fencing Type: None Fencing Condition: _____

Comment:

Corrective

Date: _____

Netting:

Netting Type: _____ Netting Condition: _____

Comment:

Corrective

Date: _____

Anchor Trench Present: _____ Oil Accumulation: _____ 2+ feet Freeboard: _____

Comment:

Corrective

Date: _____

ECMC Comments

Comment	User	Date
<p>Weather conditions: Sunny A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with ECMC rules. ECMC Inspection Report Summary On 10-30-25 at approximately 11:15 Hrs, I, Inspector Abe Serna, conducted an on-site inspection. Location: HILL RANCH 22-12V Operator: OGRIS API #: 05-071-07211 County: Las Animas While there, I observed a PR well During this inspection the following possible compliance issues were observed: Unused equipment & Impacted soil See attached photo #.2,3,4 Corrective Action Date:10-30-25 11-7-25</p> <p>This is a summary of inspection report.</p> <p>Any corrective actions from previous inspections that have not been addressed are still applicable</p>	sernaa	10/31/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404417856	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7311055
698708256	Photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7311050