

Inspection Photos

API: 011-05055

Loc: 321208

Operator: RENEGADE OIL & GAS COMPANY LLC

Inspection Date: 11/4/2025

County: Prowers



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing northeast toward the GAS PROCESSING PLANT and Wellsite.



Inspection Photos



Photo 2. Facing northwest toward the GAS PROCESSING PLANT and Wellsite.



Inspection Photos



Photo 3. Facing northwest toward the GAS PROCESSING PLANT and Wellsite. There is various supplies and debris scattered throughout the location.



Inspection Photos



Photo 4. Facing northwest at the sheds and various equipment which are in disrepair. There is still oil stained soils from the barrel that leaked out shown at red arrow.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc: 321208 | Date: 11/4/2025

Inspection Photos



Photo 5. Facing northwest at the sheds and equipment which are in disrepair.



Inspection Photos



Photo 6. Facing west at center of location. There is a birds nest inside the sheds which are in disrepair.



Inspection Photos



Photo 7. There is panels, boards, and a blue barrel laying on the ground which has leaked out fluids onto the ground.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc: 321208 | Date: 11/4/2025

Inspection Photos



Photo 8. Facing southeast at the west side of the location. This shed and fence are in disrepair with supplies have fallen out of the dilapidated shed.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc: 321208 | Date: 11/4/2025

Inspection Photos



Photo 9. Facing northeast toward the well. The fence around the pumpjack is in disrepair and there is unused equipment stored near the well.



Inspection Photos



Photo 10. Facing southwest at the wellsite. There are various unused equipment, pipe, and debris stored on location that needs to be removed.



Inspection Photos



Photo 11. Facing east at the location. There is various unused equipment, supplies and tanks stored at the location that will need to be removed.



Inspection Photos



Photo 12. Facing southwest at the location. There is various unused equipment, supplies and tanks stored at the location that will need to be removed. The soils in this area are stained with hydrocarbon impacts from historic spill.



Inspection Photos



Photo 13. Facing southeast at the location. There is various unused equipment, supplies and tanks stored at the location that will need to be removed.



Inspection Photos



Photo 14. Facing east at the south side of the location. This open top tank remains with oily fluids. Wildlife netting is installed.



Inspection Photos



Photo 15. Facing northeast the location with various unused equipment, supplies and debris laying on the ground.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc: 321208 | Date: 11/4/2025

Inspection Photos



Photo 16. Drone aerial photo taken on 2/4/2025. Facing northeast toward the GAS PROCESSING PLANT and Wellsite.



Inspection Photos



Photo 17. Drone aerial photo taken on 2/4/2025. Facing southwest toward the GAS PROCESSING PLANT and Wellsite.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc: 321208 | Date: 11/4/2025