

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/07/2025

Submitted Date:

11/07/2025

Document Number:

708907808

FIELD INSPECTION FORM

Loc ID 324204 Inspector Name: Smelser, Wayne On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10844
Name of Operator: QB ENERGY OPERATING LLC
Address: 1001 17TH STREET SUITE 1600
City: DENVER State: CO Zip: 80202

Findings:

- 2 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
QB ENERGY		ecmc.inspections@qb-energy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
264846	WELL	PR	11/04/2004	GW	045-08924	PUCKETT 255-1	PR

General Comment:

[This is a Desktop Inspection/Audit of the scout card & related documents.](#)

Inspected Facilities

Facility ID: 264846 Type: WELL API Number: 045-08924 Status: PR Insp. Status: PR

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
<p>CECMC Inspection/Audit Report Summary On 11/07/2025 at approximately 10:05 hours, I, Compliance Specialist, Wayne Smelser Conducted a desktop follow up inspection/audit of QB ENERGY OPERATING LLC PUCKETT 255-1 Location # 324204 in Garfield County Colorado. Please refer to inspection/audit 708907317 conducted on 08/25/2025, previous corrective action has been completed. Wellbore diagram submitted by operator on 10/08/2025</p> <p>This is a summary of desktop follow up inspection/audit report.</p>	smelserw	11/07/2025