

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/30/2025

Submitted Date:

11/07/2025

Document Number:

701104311

**FIELD INSPECTION FORM**

Loc ID: 421340 Inspector Name: LONGWORTH, MIKE On-Site Inspection:  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 10433  
Name of Operator: LARAMIE ENERGY LLC  
Address: 1700 LINCOLN ST STE 3950  
City: DENVER State: CO Zip: 80203

**Findings:**

- 5 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
COGCC, Laramie	970-248-0497	cogccnotifications@laramie-energy.com	All inspections
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
Wheeler, Steven		steven.wheeler@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
421341	WELL	PR	04/30/2012	GW	045-20360	Cascade Creek 697-05-28B	EG

**General Comment:**

Flowline Integrity Inspection (Follow Up)  
From 08/22/2025 inspection 701104244: 2 Frac lines were removed from east side location running down to the CC 0605-02 Pad ID# 323998. Top segments of frac lines were left. Unused equipment has been picked up and removed.  
From 08/22/2025 inspection 701104244: A 3" buried poly line has been cut off and left running under surface down to CC 0605-02 Pad ID# 323998. Line is open ended with no OOSLAT in place.  
No visible sign of 3" poly line at time of this inspection. Form 42 received 9/11/2025 doc # 404350746 to abandon in place.  
Timbers and tee posts left behind.  
Comply with 606 CA Date 11/22/2025

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	UNUSED EQUIPMENT		
Comment:	From 08/22/2025 inspection 701104244: 2 Frac lines were removed from east side location running down to the CC 0605-02 Pad ID# 323998. Top segments of frac lines were left.		
	Unused equipment has been picked up and removed.		
Corrective Action:		Date:	
Type	DEBRIS		
Comment:	Timbers and tee posts left behind.		
Corrective Action:	Comply with 606	Date:	11/22/2025

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 421341 Type: WELL API Number: 045-20360 Status: PR Insp. Status: EG

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
701104312	Flowline integrity inspection 701104311 photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7322984">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7322984</a>