

# State of Colorado Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:  
404428578

Date Received:  
11/08/2025

## FIR RESOLUTION FORM

**Overall Status:**

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

ECMC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 1099 18TH STREET SUITE 1500

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) Fax: ( )

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
.		<a href="mailto:rbucogccinspectionreports@chevron.com">rbucogccinspectionreports@chevron.com</a>
.		<a href="mailto:rbucogccinspectionreports@chevron.com">rbucogccinspectionreports@chevron.com</a>

ECMC INSPECTION SUMMARY:

FIR Document Number: 718800584

Inspection Date: 07/10/2025

FIR Submit Date: 07/30/2025

FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: NOBLE ENERGY INC

Company Number: 100322

Address: 1099 18TH STREET SUITE 1500

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 328219

Location Name: DUNCAN D-63N64W Number: 20SWNE County: \_\_\_\_\_

Qtrqtr: SWNE Sec: 20 Twp: 3N Range: 64W Meridian: 6

Latitude: 40.213600 Longitude: -104.571580

FACILITY - API Number: 05-123- -00 Facility ID: 328219

Facility Name: DUNCAN D-63N64W Number: 20SWNE

Qtrqtr: SWNE Sec: 20 Twp: 3N Range: 64W Meridian: 6

Latitude: 40.213600 Longitude: -104.571580

CORRECTIVE ACTIONS:

1 CA# 206561

Corrective Action: Comply with Rule 1004 to perform additional reclamation activities at the location and along the access road and perform weed management.

Date: \_\_\_\_\_

Response: CA COMPLETED

Date of Completion: 08/29/2025

Operator Comment: Mowed location and access road on 7/7/2025. Seeded location and access road on 8/29/2025. Midstream plastic or fiberglass marker post on site is a test station or access point for the underground Phillips 66/DCP pipeline. There is no above ground active equipment. Cattle in the area continue knocking it down although the tee post was re-installed.

ECMC Decision: \_\_\_\_\_

ECMC  
Representative:

--

**OPERATOR COMMENT AND SUBMITTAL**

Comment: This site is in Chevron's scheduled inspecting, maintenance and monitoring program.

--

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Jeff White

Signed: \_\_\_\_\_

Title: HSe

Date: 11/8/2025 12:05:25 AM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

**Document Number**      **Description**

<u>Document Number</u>	<u>Description</u>

Total Attach: 0 Files