

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/23/2025

Submitted Date:

10/23/2025

Document Number:

713302271

FIELD INSPECTION FORM

Loc ID 439944 Inspector Name: Kester, Michael On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 47120
Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP
Address: P O BOX 173779
City: DENVER State: CO Zip: 80217-

Findings:

- 11 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, KerrMcGee	970-515-1500	ECMCInspections@Oxy.com	all inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
439945	WELL	PR	09/09/2015	OW	123-40604	TAIPAN 1N-15HZ	PR
439947	WELL	PR	02/01/2024	OW	123-40605	TAIPAN 27C-15HZ	PR

General Comment:

[well site inspection](#)

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	good, two wells		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		Date:	
Corrective Action:			

Overall Good:

Spills:

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	WELLHEAD		
Comment:	metal panels		
Corrective Action:		Date:	

Equipment:

Type: Plunger Lift	# 2		corrective date
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 2		
Comment:	piped to surface, two wells		
Corrective Action:		Date:	
Type: Ancillary equipment	# 4		
Comment:	automation/electric panels		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 439945 Type: WELL API Number: 123-40604 Status: PR Insp. Status: PR

Producing Well

Comment: Valves appeared to be closed at time of inspection

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 07/11/2024 Annual Brhd Completed? No

Last Brhd Test Results Initial Surf Csg Pressure: 1 Fluid Type: None

End Surf Csg Pressure: --

Comment: Required reports not filed. Submit Bradenhead report Last Bradenhead test report submitted 7-11-24 11/24/2025

Corrective Action: Comply with Rule 207 Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 439947 Type: WELL API Number: 123-40605 Status: PR Insp. Status: PR

Producing Well

Comment: Valves appeared to be closed at time of inspection

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 07/11/2024 Annual Brhd Completed? No

Last Brhd Test Results Initial Surf Csg Pressure: 1 Fluid Type: None

End Surf Csg Pressure: --

Comment: Required reports not filed. Submit Bradenhead report Last Bradenhead test report submitted 7-11-24 11/24/2025

Corrective Action: comply with Rule 207 Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
<p>Inspector Michael Kester, did audit scout card and related documents conducted on-site inspection.</p> <p>Location: Taipan 27C-15Hz Operator: Kerr McGee API#: 123-40605 County: Weld</p> <p>While there, I observed well site with equipment. During this inspection the following possible compliance issues were observed:</p> <p>Bradenead test reporting Rule 207, corrective action date 11-24-2025, two wells on site</p> <p>Weather conditions: sunny and dry</p> <p>A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with ECMC rules. This inspection does not nullify any orders or NOAV from the ECMC</p>	kesterm	10/23/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404403150	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7294538
713302272	site pic	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7294536