

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/29/2025

Submitted Date:

11/03/2025

Document Number:

708907782

FIELD INSPECTION FORM

Loc ID 335364 Inspector Name: Smelser, Wayne On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 96850
Name of Operator: TEP ROCKY MOUNTAIN LLC
Address: 1058 COUNTY ROAD 215
City: PARACHUTE State: CO Zip: 81635

Findings:

21 Number of Comments
1 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
TEP		ECMCInspectionReports@flywheelenergy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
257840	WELL	PR	11/07/2002	GW	045-07602	UNOCAL GM 31-33	PR
271847	WELL	PR	07/07/2004	GW	045-09967	WILLIAMS GM 216-33	PR
271851	WELL	PR	07/12/2004	GW	045-09971	WILLIAMS GM 531-33	PR
271852	WELL	PR	07/08/2004	GW	045-09972	WILLIAMS GM 431-33	PR

General Comment:

This is a Field Inspection/Audit of the scout card, related documents and the location.

Location			
Lease Road:			
Type	Access		
comment:			
Corrective Action:			Date:
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
Type	BATTERY		
Comment:			
Corrective Action:			Date:
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass located on the side of the units indicates the storage tanks are full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tanks.		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	911/970-285-9377		
Corrective Action:			Date: _____
Good Housekeeping:			
Type	DEBRIS		
Comment:	Debris - please refer to photo log		
Corrective Action:			Date:
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No _____			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	WELLHEAD		
Comment:	Hog panels		
Corrective Action:			Date:
Type	TANK BATTERY		
Comment:	Hog panels		

Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Hog panels		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Gas Meter Run	# 4		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 1		
Comment:	Marked		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 4		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 4		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 4		
Comment:	All wells on plunger lift		
Corrective Action:		Date:	
Type: Bradenhead	# 4		
Comment:	WILLIAMS GM 216-33 has Taylor plug located on bradenhead, bradenhead valve is accessible Remaining 3 wells have no form of pressure monitoring equipment located on bradenheads, bradenhead valves are accessible		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Open ended load line		
Corrective Action:	Comply with CECMC Rule 603	Date:	11/10/2025

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	200 BBLS	STEEL AST		,
Comment:	Tank equipped with telemetry				
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
------	----------	---------------------	---------------------	-------------

Metal	Adequate	Walls Sufficent			
Comment:					
Corrective Action:				Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities			
Facility ID: <u>257840</u>	Type: <u>WELL</u>	API Number: <u>045-07602</u>	Status: <u>PR</u> Insp. Status: <u>PR</u>
Producing Well			
Comment:	Producing, well on plunger lift		
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID: <u>271847</u>	Type: <u>WELL</u>	API Number: <u>045-09967</u>	Status: <u>PR</u> Insp. Status: <u>PR</u>
Producing Well			
Comment:	Producing, well on plunger lift		
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID: <u>271851</u>	Type: <u>WELL</u>	API Number: <u>045-09971</u>	Status: <u>PR</u> Insp. Status: <u>PR</u>
Producing Well			
Comment:	Producing, well on plunger lift		
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID: <u>271852</u>	Type: <u>WELL</u>	API Number: <u>045-09972</u>	Status: <u>PR</u> Insp. Status: <u>PR</u>
Producing Well			
Comment:	Producing, well on plunger lift		
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Check Dams				
		Compaction				Light compaction in some areas
Compaction						Light compaction in some areas
		Gravel				Sparse to none
		Culverts				
Gravel						Sparse to none in most areas
		Ditches				

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
<p>CECMC Inspection/Audit Report Summary On 10/29/2025 at approximately 14:24 hours, I, Compliance Specialist, Wayne Smelser Conducted a follow up inspection/audit at TEP ROCKY MOUNTAIN LLC UNOCAL GM 31-33 Pad Location # 335364 in Garfield County Colorado. Please refer to inspection/audit 719500284 conducted on 07/24/2025, previous corrective action has been completed. Location is within High Priority/Density/NSO/Black Bear Habitat areas. Location is approximately 116 yards from Parachute Creek. While there, I observed normal production operations.</p> <p>During this inspection/audit the following compliance issues were observed:</p> <p>1. Equipment - Open ended load line - Comply with rule 603 with a CA date of 11/10/2025</p> <p>Comments -</p> <p>Housekeeping - Debris</p> <p>A follow up on this site inspection/audit needs to be conducted to ensure the compliance issues have been corrected to comply with CECMC rules. This is a summary of inspection/audit report.</p>	smelserw	11/03/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404420742	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7314613
708907783	Inspection/Audit 708907782 Stormwater photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7314611
708907784	Inspection/Audit 708907782 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7314612