

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/03/2025

Submitted Date:

11/03/2025

Document Number:

713302304

FIELD INSPECTION FORM

Loc ID 336292 Inspector Name: Kester, Michael On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 46290
Name of Operator: KP KAUFFMAN COMPANY INC
Address: 1700 LINCOLN ST STE 4550
City: DENVER State: CO Zip: 80203

Findings:

- 11 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Santistevan, Brittani		brittani.santistevan@state.co.us	
, KPK	303-825-4822	cogcc@kpk.com	all inspections
,		conor.pesicka@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
241704	WELL	SI	04/01/2021	GW	123-09493	MILTON H. NELSON UNIT B 1	SI

General Comment:

[follow up inspection](#)

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	good		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:			
Corrective Action:		Date:	_____

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	dissassembled pumping unit on site		
Corrective Action:	Comply with Rule 606	Date:	04/13/2024

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment: _____

Multiple Spills and Releases?

Equipment:

Type	#	Comment	Corrective Action	Date	corrective date
Bradenhead	# 1	Comment: piped to surface			
Prime Mover	# 0	Comment: REMOVED			
Pump Jack	# 1	Comment: Dissassembled on site			
Ancillary equipment	# 3	Comment: automation/electric panels			

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			

Corrective Action:

Date:

Inspected Facilities

Facility ID: 241704 Type: WELL API Number: 123-09493 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: EQUIPMENT ONSITE

Comment: Valves appeared to be closed at time of inspection
Well shutin in accordance with Rule 901a,

Corrective Action: Date:

BradenHead

Date of Last Brhd Test: 05/13/2024 Annual Brhd Completed? No

Last Brhd Test Results Initial Surf Csg Pressure: 5 Fluid Type:

End Surf Csg Pressure: 0

Comment: Required reports not filed, Submit Bradenhead report Last Bradenhead test report submitted 5-13-24 12/03/2025

Corrective Action: Comply with Rule 207 Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
Inspector Michael Kester, did audit scout card and related documents conducted an follow up on-site inspection, doc 715801271 Location: Milton H Nelson Unit B1 Operator: KPK API#: 123-09493 County: Weld While there, I observed well site with pumping unit. During this inspection the following possible compliance issues were observed: Well shutin in accordance with Rule 901a, Unused equipment, Comply with 606, corrective action date 4-13-2024 Weather conditions: sunny and dry A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with ECMC rules. This inspection does not nullify any orders or NOAV from the ECMC	kesterm	11/03/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404421641	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7315712
713302305	site pic	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7315708