

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/30/2025

Submitted Date:

11/03/2025

Document Number:

718300093

**FIELD INSPECTION FORM**

Loc ID 430790 Inspector Name: Anderson, Laurel On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 69175  
Name of Operator: PDC ENERGY INC  
Address: 1099 18TH STREET SUITE 1500  
City: DENVER State: CO Zip: 80202

**Findings:**

- 8 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

| Contact Name    | Phone | Email   | Comment                         |
|-----------------|-------|---|---------------------------------|
| Rollins, Grace  |       | grace.rollins@state.co.us                         |                                 |
| Graber, Nikki   |       | nikki.graber@state.co.us                          |                                 |
| ,               |       | rbucogccinspectionreports@chevron.onmicrosoft.com | <a href="#">All Inspections</a> |
| Brown, Kari     |       | kari.oakman@state.co.us                           |                                 |
| Dunnam, Anthony |       | anthony.dunnam@state.co.us                        |                                 |
| Peterson, Dan   |       | danpeterson@chevron.com                           |                                 |

**Inspected Facilities:**

| Facility ID | Type             | Status | Status Date | Well Class | API Num   | Facility Name                   | Insp Status |
|-------------|------------------|--------|-------------|------------|-----------|---------------------------------|-------------|
| 430790      | LOCATION         | AC     | 09/17/2025  |            | -         | Campbell JF PAD 17-41D          | EI          |
| 430904      | WELL             | TA     | 06/25/2024  | OW         | 123-36324 | Campbell JF 17-41D              | TA          |
| 460607      | TANK BATTERY     | AC     | 01/10/2019  |            | -         | Campbell JF PAD /17-41D battery | EI          |
| 491381      | SPILL OR RELEASE | AC     | 09/17/2025  |            | -         | Campbell JF PAD 17-41D          | EI          |

**General Comment:**

This is an ECMC Environmental Field Inspection to determine progress on Spill ID 491381 and Remediation Project #33091. Any corrective actions from previous inspections, NOAVs and/or conditions of approval from previous forms that have not been fully addressed are still applicable. There were no operator or contract environmental personnel on location at the time of this field inspection. Photos attached to document site conditions.

Campbell JF PAD 17-41 (Location ID 430790)

Campbell JF PAD 17-41D battery (Facility ID 460607)

Campbell JF 17-41D Well (API 123-36324)

Spill Name: Campbell JF PAD 17-41

Spill ID: 491381

Spill Details: On 9/9/2025, the potential presence of impacted material(s) was identified via hydrocarbon odor and hydrocarbon staining during decommissioning activities at the Campbell JF PAD 17-41D, tank battery, sample: SEP03-DL, located at the separator dumpline. The volume of potentially impacted material(s) is not currently known.

Reported Date of Discovery: 9/9/2025

Remediation Project #33091 - Operator is behind on quarterly reporting for REM 33091.

Current site status:

-The excavation associated with soil sampling at the separator dumpline (SEP03-DL@5') and visible in photo documentation attached to Form 19i Doc #404348902 and associated with Spill ID 491381 was not observed during ECMC's inspection and appears to have been backfilled to grade.

-Campbell 17-41D wellhead appears to have been P&A'd and surface equipment removed. No open excavation or soil stockpiles were observed. Signage and cattle fencing installed around the Campbell 17-41D wellhead has been removed.

-The tank battery has been decommissioned; 3rd party meter shed remains on location

-Majority of weeds that were observed on 9/15/2025 around the perimeter of the location and along the lease road (see FIR Doc #718300064) have been removed.

-Portable restroom on location that had toppled over prior to the previous inspection on 9/15/2025 (see FIR Doc #718300064) has been removed.

See attached corrective actions.

**Location**

Overall Good:

**Signs/Marker:**

|                    |   |       |  |
|--------------------|---|-------|--|
| Type               | BATTERY   |       |  |
| Comment:           | Tank battery signage was observed during this field inspection. |       |  |
| Corrective Action: |   | Date: |  |

Emergency Contact Number:

|                    |                      |       |  |
|--------------------|----------------------|-------|--|
| Comment:           | <input type="text"/> | Date: |  |
| Corrective Action: | <input type="text"/> | Date: |  |

**Good Housekeeping:**

|                    |   |       |  |
|--------------------|---|-------|--|
| Type               | WEEDS   |       |  |
| Comment:           | Majority of weeds that were observed on 9/15/2025 around the perimeter of the location and along the lease road (see FIR Doc #718300064) have been removed. |       |  |
| Corrective Action: |   | Date: |  |
| Type               | OTHER   |       |  |
| Comment:           | Portable restroom on location that had toppled over prior to the previous inspection on 9/15/2025 (see FIR Doc #718300064) has been removed.                |       |  |
| Corrective Action: |   | Date: |  |

Overall Good:

**Spills:**

| Type | Area | Volume |  |  |
|------|------|--------|--|--|
|      |      |        |  |  |

In Containment: No

Comment:

Multiple Spills and Releases?

**Venting:**

|                    |  |       |  |
|--------------------|--|-------|--|
| Yes/No             |  |       |  |
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |

**Flaring:**

|                    |  |       |  |
|--------------------|--|-------|--|
| Type               |  |       |  |
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |

**Inspected Facilities**

Facility ID: 430790 Type: LOCATION API Number: - Status: AC Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12

Facility ID: 430904 Type: WELL API Number: 123-36324 Status: TA Insp. Status: TA

The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12

Facility ID: 460607 Type: TANK API Number: - Status: AC Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12

Facility ID: 491381 Type: SPILL OR API Number: - Status: AC Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12

**Environmental**

**Spills/Releases:**

Type of Spill: \_\_\_\_\_ Estimated Spill Volume: \_\_\_\_\_

Comment: The excavation associated with soil sampling at the separator dumpline (SEP03-DL@5') and visible in photo documentation attached to Form 19i Doc #404348902 and associated with Spill ID 491381 was not observed during ECMC's inspection and appears to have been backfilled to grade.

Corrective Action: CA Outstanding - Operator shall provide all waste manifests as required by Rule 905.b.(3) for oily waste hauled off site for disposal. Additionally, Operator shall provide all tickets for material hauled on site for backfill. This documentation shall be included on the next Supplemental Form 27. Date: \_\_\_\_\_

Reportable: \_\_\_\_\_ GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_

Proximity to Surface Water: \_\_\_\_\_ Depth to Ground Water: \_\_\_\_\_

**Water Well Complaint:**

DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_ Lat \_\_\_\_\_ Long \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_ Comment: \_\_\_\_\_

**Spill/Remediation:**

Comment: Spill ID 491381 was created to address the remediation of impacts identified at the separator dumpline (SEP03-DL@5'). Remediation Project #33091 was created for decommissioning of the Campbell JF PAD 17-41 (Location ID 430790) including the Campbell JF PAD 17-41D battery (Facility ID 460607), Campbell JF 17-41D Well (API 123-36324) and associated off-location flowline. This spill/release report will remain unresolved until a Supplemental Form 27 is approved under the existing Remediation Project #33091. The Supplemental Form 27 shall include an updated implementation schedule in addition to proposed specific actions to address the identified release. Note: Operator are required to investigate impacts to soil, groundwater, and surface water as soon as impacts are discovered in accordance with Rule 913.d.(1).

Corrective Action: Quarterly reporting is required for REM 33091. Operator is behind on quarterly reporting. The last Form 27s (Doc #404264879) was received on 7/04/2025. In accordance with Rule 913.e.(3), Operator will adopt a quarterly reporting schedule (every 90 days); additional violations may result in enforcement. CA due date backdated to when the quarterly Form 27s was due. Date: 10/02/2025

Emission Control Burner (ECB): \_\_\_\_\_

Comment:

Pilot: \_\_\_\_\_ Wildlife Protection Devices (fired vessels): \_\_\_\_\_

**ECMC Comments**

| Comment   | User      | Date       |
|---|-----------|------------|
| Date of Inspection: 10/30/2025<br>Weather: Clear, slight breeze <5mph, 48°F<br>PPE: Level D & FR Clothing | andersoln | 11/03/2025 |

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description                               | URL   |
|--------------|---|---|
| 404420907    | INSPECTION SUBMITTED                      | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7314752">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7314752</a> |
| 718300094    | 2025_1030_Campbell JF PAD 17-41 Photo Log | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7314751">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7314751</a> |