

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/03/2025

Submitted Date:

11/03/2025

Document Number:

719000852

FIELD INSPECTION FORM

Loc ID 333934 Inspector Name: GARCIA, CHARLES On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10133
Name of Operator: HILCORP ENERGY COMPANY
Address: P O BOX 61229
City: HOUSTON State: TX Zip: 77208

Findings:

- 15 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, General		FarmingtonRegulatoryTechs@hilcorp.com	SJB inspect
Labowskie, Steve		steve.labowskie@state.co.us	
Kosola, Jason		jason.kosola@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
258202	WELL	PR	12/01/2010	CBM	067-08335	SQUIRES 2	PR
301405	WELL	PR	11/16/2009	CBM	067-09702	SQUIRES 3	PR

General Comment:

Inspection Report Summary
On 11/3/25 | Inspector Charles Garcia conducted an on-site inspection.
Location: SQUIRES #3,#2
API# 067-09702 API# 067-08335
Operator: HILLCORP ENERGY COMPANY
County: LaPlata

Location

Overall Good:

Signs/Marker:

Type	TANK LABELS/PLACARDS		
Comment:	PRODUCED WATER TANK		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	LOCATION SIGN AT ENTERANCE		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 24 Hr #970-247-6916
Emergency #911

Corrective Action:

Date:

Good Housekeeping:

Type	STORAGE OF SUPL		
Comment:	LAND OWENER HAS EQUIPMENT ON LOCATION SEE LOCATION PICTURES		
Corrective Action:		Date:	

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	SEPARATOR		
Comment:	CATTLE PANELS		
Corrective Action:		Date:	
Type			
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	CATTLE PANELS		
Corrective Action:		Date:	
Type	PUMP JACK		
Comment:	CATTLE PANELS		
Corrective Action:		Date:	
Type	OTHER		
Comment:	PRODUCED WATER TANK HOG WIRE METER HOUSE CATTLE PANELS		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Bradenhead	# 2		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 4		
Comment:	TELEMETRY EQUIPMENT LUBE OIL CONTAINERS FOR PRIME MOVERS		
Corrective Action:			Date:
Type: Pump Jack	# 2		
Comment:			
Corrective Action:			Date:
Type: Other	# 1		
Comment:	METER HOUSE CALIBRATION IN COMPLIANCE		
Corrective Action:			Date:
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:			Date:
Type: Prime Mover	# 2		
Comment:	GAS		
Corrective Action:			Date:
Type: Flow Line	# 2		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 2		
Comment:			
Corrective Action:			Date:
Type: Vertical Heated Separator	# 2		
Comment:			
Corrective Action:			Date:
Type: Other	# 2		
Comment:	WELLHEAD ON THE SQUIRES #3 HAD LEAK ON STUFFING BOX APROX 3 BBLs PRODUCED WATER SPILLED ONTO LOCATION MEASUREMENTS 50 FT LONG 12 FT WIDE 5IN INTO SOIL SEE LOCATION PICTURES		
Corrective Action:	CONTROL SPILL AND CLEAN UP FREE FLUIDS WITHIN 24 HRS SUBMIT FORM 19 WITHIN 24 HRS AND CONTACT JASON KOSOLA WITHIN 72 HOURS PER RULE 906		Date: 11/03/2025

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1				37.043300,-107.553900
Comment:	60 BBL PRODUCED WATER TANK				
Corrective Action:					Date:

Paint

Condition	Adequate
-----------	----------

Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO			
Comment:				
Corrective Action:				
				Date:

Flaring:

Type				
Comment:				
Corrective Action:				
				Date:

Inspected Facilities

Facility ID: 258202 Type: WELL API Number: 067-08335 Status: PR Insp. Status: PR

Producing Well

Comment:

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 06/10/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type:

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 301405 Type: WELL API Number: 067-09702 Status: PR Insp. Status: PR

Producing Well

Comment:

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 06/10/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type:

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404420635	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7314536
719000856	LOCATION PICTURES	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7314531